



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA HDI (110BHP) DESIRE PICASSO
Colour	Blue
Year of manufacture	2004
Top speed	114 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-11-02
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-28
MOT pass rate	69 %
MOT passed	18
Failed MOT tests	8
Total advice items	69
Total items failed	32

MOT #26	2023-10-12 10:21
MOT test number	559849664651
Result	✓ Passed
Next expiry date	2024-10-28
Advice	Front Registration plate deteriorated but not likely to be misread damaged (0.1 (b))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #25**

2023-10-11 09:39

MOT test number

820077566414

Result**✗ Failed****Advice** Front Registration plate deteriorated but not likely to be misread damaged (0.1 (b))**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Rear Brake pipe excessively corroded from union to flexi hose (1.1.11 (c))**Fail** Offside Rear Brake pipe excessively corroded from flexi to flexi (1.1.11 (c))**Fail** Offside Front Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Rear Brake pipe excessively corroded from flexi to flexi at wheel (1.1.11 (c))**MOT #24**

2022-10-25 12:56

MOT test number

533619065639

Result**✓ Passed****Advice** Play in steering rack inner joint(s)**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge very close (5.2.3 (e))**Minor** Offside Side repeater lens defective which has no effect on emitted light missing (4.4.1 (b) (i))**Advice** Rear axle corroded

**MOT #23**

2022-10-17 13:06

MOT test number

728029403993

Result**✗ Failed**

- Minor** Offside Side repeater lens defective which has no effect on emitted light missing (4.4.1 (b) (i))
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Suspension arm attachment bracket/mounting likely to fail rearmost bolt missing (5.3.3 (b) (ii))
- Fail** Nearside Rear Inner Brake hose excessively deteriorated (1.1.12 (b) (ii))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Rear axle corroded
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Offside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge very close (5.2.3 (e))
- Minor** Nearside Registration plate lamp missing in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule both hoses (1.1.12 (f) (i))
- Advice** Offside Rear Inner Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #22**

2021-10-29 15:25

MOT test number

837056347007

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Sill Damaged
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pipe corroded, covered in grease or other material Both Sides To Hose (1.1.11 (c))

MOT #21

2021-10-29 10:44

MOT test number

896610563428

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material Both Sides To Hose (1.1.11 (c))
- Fail** Offside Side repeater incorrect colour (4.4.3 (a))
- Advice** Nearside Rear Sill Damaged
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn Front Inner Bush (5.3.4 (a) (i))

**MOT #20**

2020-12-17 09:55

MOT test number

162036388601

Result

✓ Passed

- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #19

2020-12-04 16:57

MOT test number

136052071908

Result

✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (ii))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #18**

2019-12-04 16:22

MOT test number

649939395425

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Rear wiper deteriorated
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17

2019-12-04 15:11

MOT test number

341006959962

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))
- Advice** Rear wiper deteriorated

MOT #16

2018-12-07 15:00

MOT test number

658650431253

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2018-12-07 12:07**MOT test number** 615940574504**Result** ✗ Failed**Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #14** 2017-12-08 15:53**MOT test number** 746863382063**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #13** 2017-12-07 17:23**MOT test number** 226469639649**Result** ✗ Failed**Fail** Offside Obligatory mirror insecure (8.1.1)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** NOTE unable to see front outer brake pads**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions Rotation (4.1.D.1f)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #12** 2017-01-12 12:25**MOT test number** 652654988737**Result** ✓ Passed**Advice** Nearside front tyre on approx 3mm**Advice** Unable to clearly see front brake pad thickness**MOT #11** 2017-01-12 08:54**MOT test number** 372313867103**Result** ✗ Failed**Advice** Unable to clearly see front brake pad thickness**Fail** Nearside Rear Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)**Advice** Nearside front tyre on approx 3mm**Fail** Central Rear Seat belt damaged sufficient to obstruct correct operation of the belt (5.2.2a)**MOT #10** 2016-01-11 10:04**MOT test number** 131177641344**Result** ✓ Passed**MOT #9** 2015-01-12 14:31**MOT test number** 168582715085**Result** ✓ Passed**MOT #8** 2014-01-10 16:25**MOT test number** 659100714096**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #7	2013-01-11 13:03
MOT test number	937631113004
Result	✓ Passed
MOT #6	2012-01-04 12:49
MOT test number	887744902081
Result	✓ Passed
MOT #5	2011-01-05 12:54
MOT test number	119145401099
Result	✓ Passed
MOT #4	2010-01-07 12:57
MOT test number	542787600056
Result	✓ Passed
MOT #3	2009-01-14 12:32
MOT test number	322974019009
Result	✓ Passed
MOT #2	2008-02-04 09:33
MOT test number	873325638030
Result	✓ Passed
MOT #1	2007-02-14 12:44
MOT test number	170545647412
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
28 October 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	28 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2004-03-01
Last registration	2023-10-12
Complete history	See info



Registration #1	2004-03-01	7 mi
Registration #2	2007-02-14	20.102 mi
Registration #3	2008-02-04	24.591 mi
Registration #4	2009-01-14	27.367 mi
Registration #5	2010-01-07	34.306 mi
Registration #6	2011-01-05	36.504 mi
Registration #7	2012-01-04	39.671 mi
Registration #8	2013-01-11	42.688 mi
Registration #9	2014-01-10	45.671 mi
Registration #10	2015-01-12	49.153 mi
Registration #11	2016-01-11	52.217 mi
Registration #12	2017-01-12	60.351 mi
Registration #13	2017-01-12	60.351 mi
Registration #14	2017-12-07	70.627 mi
Registration #15	2018-01-01	75.000 mi
Registration #16	2018-01-01	75.000 mi
Registration #17	2018-01-01	75.000 mi
Registration #18	2018-01-01	75.000 mi
Registration #19	2018-01-01	75.000 mi
Registration #20	2018-01-01	75.000 mi
Registration #21	2018-01-01	75.000 mi
Registration #22	2018-01-01	75.000 mi
Registration #23	2018-01-01	75.000 mi
Registration #24	2018-01-01	75.000 mi
Registration #25	2018-01-01	75.000 mi
Registration #26	2018-01-01	75.000 mi

Registration #27	2025-05-20	25,000,000
Registration #28	2025-05-20	25,000,000

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1705 mm
Height	1420 mm
Length	4369 mm
Wheel base	2760 mm
Kerb weight	1313 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	JB010000930