



report date: 2024-03-28

General information

Make	SUZUKI
Model	ALTO SZ
Colour	Red
Year of manufacture	2013
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-06-04
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-13
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	29
Total items failed	7

MOT #11 2023-10-24 11:59**MOT test number** 183264944391**Result** ✓ Passed**Next expiry date** 2024-11-13**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #10** 2022-10-24 09:22**MOT test number** 259003347694**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2021-10-18 13:59**MOT test number** 161045523946**Result** ✓ Passed

**MOT #8** 2020-10-22 14:03**MOT test number** 861379309547**Result** ✓ Passed**Advice** Front bumper damaged**Advice** Clutch biting point high**Advice** Rear bumper damaged**MOT #7** 2020-10-22 08:26**MOT test number** 683645390042**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear bumper damaged**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front bumper damaged**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Clutch biting point high**MOT #6** 2019-11-09 15:06**MOT test number** 532767973580**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Clutch biting point high**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5**

2019-11-09 09:53

MOT test number

287248229866

Result

✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Clutch biting point high
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #4

2018-11-11 11:40

MOT test number

525195882742

Result

✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Items removed from driver's view prior to test
- Minor** Front Drive shaft joint constant velocity boot severely deteriorated bothsides inner (6.1.7 (g) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3

2017-11-11 15:51

MOT test number

916093342179

Result

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2017-11-11 09:06
MOT test number	866057760692
Result	✗ Failed
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2016-11-14 10:44
MOT test number	238832336231
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Both rear and offside front tyres are perishing



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
13 November 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	13 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-06-28
Last registration	2023-10-24
Complete history	See info



Registration #1	2013-06-28	23 mi
Registration #2	2016-11-14	12.738 mi
Registration #3	2017-11-11	18.084 mi
Registration #4	2017-11-11	18.086 mi
Registration #5	2018-11-11	24.214 mi
Registration #6	2019-11-09	28.667 mi
Registration #7	2019-11-09	28.667 mi
Registration #8	2019-11-09	28.667 mi
Registration #9	2019-11-09	28.667 mi
Registration #10	2019-11-09	28.667 mi
Registration #11	2019-11-09	28.667 mi
Registration #12	2019-11-09	28.667 mi
Registration #13	2019-11-09	28.667 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1640153