



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM SE
Colour	Red
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	I







Internet history

Entry 2


Date	2021-07-24
Pictures	40
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-07-14
Pictures	9
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-12-09
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	27
Total items failed	3

## MOT #10 2023-11-27 12:35

MOT test number 121065778614

Result ✓ Passed

Next expiry date 2024-12-09

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

## MOT #9 2022-12-05 12:41

MOT test number 589536022916

Result ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

## MOT #8 2021-12-10 16:16

MOT test number 704467304296

Result ✓ Passed

- Advice** Rear Oil leak, but not excessive diff seal weeping (8.4.1 (a) (i))
- Advice** Offside Front Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #7** 2021-12-10 14:35**MOT test number** 139343609459**Result** ✗ Failed**Advice** Rear Oil leak, but not excessive diff seal weeping (8.4.1 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #6** 2020-12-04 12:56**MOT test number** 394746996494**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2019-11-13 10:15**MOT test number** 937649828624**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #4**

2019-11-12 14:39

**MOT test number**

803386274773

**Result****✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #3**

2018-12-06 12:20

**MOT test number**

185563190945

**Result****✓ Passed****Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on the edges (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on the edges (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2**

2017-12-08 13:02

**MOT test number**

567588357884

**Result****✓ Passed****Advice** Nearside Front Tyre deteriorating and worn on edges and worn on outer edge**Advice** Offside Front Tyre deteriorating and worn on edges and worn on outer edge



MOT #1	2016-12-09 09:31
MOT test number	615825121429
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
9 December 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	9 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-12-09
Last registration	2023-11-27
Complete history	<a href="#">See info</a>



Registration #1	2013-12-09	29 mi
Registration #2	2016-12-09	29.262 mi
Registration #3	2017-12-08	38.067 mi
Registration #4	2018-12-06	43.917 mi
Registration #5	2019-11-12	49.475 mi
Registration #6	2019-11-13	49.475 mi
Registration #7	2020-12-04	55.850 mi
Registration #8	2021-11-27	55.850 mi
Registration #9	2021-11-27	55.850 mi
Registration #10	2021-11-27	55.850 mi
Registration #11	2021-11-27	55.850 mi
Registration #12	2021-11-27	55.850 mi
Registration #13	2023-11-27	55.850 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1880 mm
Height	1680 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	2001 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	D4HBDU824233