



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	VECTRA EXCLUSIV CDTI 16V
Colour	Silver
Year of manufacture	2008
Top speed	135 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1	
Date	2021-07-03
Pictures	17
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-04
MOT pass rate	58 %
MOT passed	14
Failed MOT tests	10
Total advice items	22
Total items failed	23

MOT #24	2023-06-05 12:43
MOT test number	772965784533
Result	✓ Passed
Next expiry date	2024-06-04
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))

MOT #23	2023-06-02 10:13
MOT test number	425747124079
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Rear Hydraulic brake calliper insecurely mounted (1.1.16 (c) (i))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Rear Exhaust system insecure x2 (6.1.2 (a))
Advice	Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**MOT #22**

2022-07-05 16:29

**MOT test number**

338685846793

**Result**

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases front flexi pipe (6.1.2 (a))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #21**

2022-07-01 11:47

**MOT test number**

875512454498

**Result**

✗ Failed

- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Exhaust has a minor leak of exhaust gases front flexi pipe (6.1.2 (a))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #20**

2021-06-08 14:54

**MOT test number**

848041475243

**Result**

✓ Passed

**MOT #19** 2021-05-25 14:10**MOT test number** 672952927254**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #18** 2020-06-24 12:28**MOT test number** 247167335033**Result** ✓ Passed**MOT #17** 2020-06-24 10:17**MOT test number** 123717099283**Result** ✗ Failed**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #16** 2019-06-11 13:58**MOT test number** 496053977318**Result** ✓ Passed**MOT #15** 2019-06-11 13:58**MOT test number** 139025980269**Result** ✗ Failed**Pass with rectification** Offside Obligatory mirror does not provide a view to the rear (3.3 (c))

**MOT #14** 2018-06-12 15:42**MOT test number** 838851047435**Result** ✓ Passed**MOT #13** 2017-06-30 11:52**MOT test number** 455202867821**Result** ✓ Passed**Advice** Offside Front Inner Play in steering rack inner joint(s)**MOT #12** 2017-06-30 07:45**MOT test number** 215097454395**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)**Advice** Offside Front Inner Play in steering rack inner joint(s)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)**MOT #11** 2016-06-28 13:17**MOT test number** 295852865044**Result** ✓ Passed**MOT #10** 2016-06-28 08:08**MOT test number** 993892413682**Result** ✗ Failed**Fail** Nearside Front coil spring broken (2.4.C.1a)

**MOT #9** 2015-07-08 12:56**MOT test number** 197049285160**Result** ✓ Passed**MOT #8** 2014-07-30 12:15**MOT test number** 238761714270**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #7** 2014-07-30 12:15**MOT test number** 897061514221**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2013-07-30 09:07**MOT test number** 897971113273**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #5** 2013-07-30 09:07**MOT test number** 397861913232**Result** ✓ Passed

**MOT #4** 2012-08-09 12:57**MOT test number** 288022222242**Result** ✓ Passed**Notice** Plastic outer sill covers fitted**MOT #3** 2012-08-09 12:57**MOT test number** 987272722260**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high and too far to the right. (1.8)**Notice** Plastic outer sill covers fitted**MOT #2** 2011-08-05 09:51**MOT test number** 347627311411**Result** ✓ Passed**MOT #1** 2011-01-20 14:49**MOT test number** 946000721007**Result** ✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
4 June 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	4 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 BF57EFW
Plate since	2019-06-29
Current registration	 BF57EFW
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-01-29
Last registration	2023-06-05
Complete history	<a href="#">See info</a>



Registration #1	2008-01-29	18 mi
Registration #2	2011-01-20	73.160 mi
Registration #3	2011-08-05	73.286 mi
Registration #4	2012-08-09	76.778 mi
Registration #5	2013-07-30	80.135 mi
Registration #6	2014-07-30	83.512 mi
Registration #7	2015-07-08	86.953 mi
Registration #8	2016-06-28	96.995 mi
Registration #9	2016-06-28	96.999 mi
Registration #10	2017-06-30	105.536 mi
Registration #11	2017-06-30	105.536 mi
Registration #12	2018-06-12	111.526 mi
Registration #13	2019-06-28	111.526 mi
Registration #14	2019-06-28	111.526 mi
Registration #15	2019-06-28	111.526 mi
Registration #16	2019-06-28	111.526 mi
Registration #17	2019-06-28	111.526 mi
Registration #18	2019-06-28	111.526 mi
Registration #19	2019-06-28	111.526 mi
Registration #20	2019-06-28	111.526 mi
Registration #21	2019-06-28	111.526 mi
Registration #22	2019-06-28	111.526 mi
Registration #23	2019-06-28	111.526 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1428 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	17390132