



report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 350 H/R P/V
Colour	White
Year of manufacture	2012
Gearbox	6 speed Manual

Engine & fuel consumption

Power	153 BHP
Max. torque	385 Nm at 1.600 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	38.2 mpg
Consumption combined	34.9 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2024-11-15
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	30
Total items failed	7

MOT #12	2023-11-02 13:00
MOT test number	815247764853
Result	✓ Passed
Next expiry date	2024-11-15
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 215-75-16c (5.2.3 (e))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 215-75-16c (5.2.3 (e))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2022-11-16 12:46
MOT test number	525082041740
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10**

2022-11-04 14:35

MOT test number

918108783478

Result**✗ Failed****Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail

Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))

Fail

Exhaust diesel particulate filter shows evidence of tampering. (8.2.2.1 (c))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail

Nearside Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting outer sill (6.2.2 (d) (i))

MOT #9

2021-11-11 11:03

MOT test number

679046316237

Result**✓ Passed****Advice**

Nearside Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Advice

Offside Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))

Advice

Nearside Outer sill has a hole outside of prescribed area

MOT #8

2021-02-25 14:58

MOT test number

284253925989

Result**✓ Passed**

**MOT #7**

2020-12-08 13:00

MOT test number

367041439274

Result**✗ Failed****Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside rear hub seal slight leak**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Brake pipe corroded, covered in grease or other material across axle (1.1.11 (c))**MOT #6**

2019-12-12 09:49

MOT test number

132913542783

Result**✓ Passed****Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Central Rear Brake pipe corroded, covered in grease or other material across rear axle (1.1.11 (c))**MOT #5**

2019-12-11 15:45

MOT test number

181813002754

Result**✗ Failed****Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Central Rear Brake pipe corroded, covered in grease or other material across rear axle (1.1.11 (c))**Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #4** 2017-11-21 12:01**MOT test number** 162307863831**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #3** 2016-12-22 09:16**MOT test number** 799902221063**Result** ✓ Passed**Advice** Eml warning light on**Advice** Slight noise front offside wheel bearing**MOT #2** 2015-12-09 09:23**MOT test number** 188879791242**Result** ✓ Passed**MOT #1** 2014-12-16 15:54**MOT test number** 338060154387**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
15 November 2024

Tax status	Valid until 1 March
-------------------	---------------------

Days left	307
------------------	-----

MOT expiry date	15 November 2024
------------------------	------------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-01-01
Last registration	2023-11-02
Complete history	See info



Registration #1	2012-01-01	26 mi
Registration #2	2014-12-16	53.395 mi
Registration #3	2015-12-09	63.041 mi
Registration #4	2016-12-22	78.035 mi
Registration #5	2017-11-21	92.489 mi
Registration #6	2019-12-11	104.206 mi
Registration #7	2019-12-12	104.211 mi
Registration #8	2019-12-12	104.211 mi
Registration #9	2019-12-12	104.211 mi
Registration #10	2019-12-12	104.211 mi
Registration #11	2019-12-12	104.211 mi
Registration #12	2019-12-12	104.211 mi
Registration #13	2019-12-12	104.211 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	CB51893