





report date: 2024-03-29

## General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 SPORTIVE CDTI
Colour	Silver
Year of manufacture	2018
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	47.1 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



report date: 2024-03-29

# Internet history


### Entry 3

Date 2021-09-10

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 2

Date	2021-07-10
------	------------

Pictures 21

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1

Date 2021-06-04

Pictures 20

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



report date: 2024-03-29

# MOT history

MOT expiry date	2025-02-24
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #5	2024-02-06 09:35
MOT test number	131495391495
Result	✓ Passed
Next expiry date	2025-02-24
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #4	2023-02-06 15:39
MOT test number	335339000066
Result	✓ Passed
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #3	2023-02-06 10:16
MOT test number	968471029707
Result	<b>X</b> Failed
Fail Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))  Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))  Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2022-02-21 10:56

**MOT test number** 744709844601

**Result** ✓ Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #1 2021-02-25 09:45

**MOT test number** 509516248378

**Result** ✓ Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 4/11



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	24 February 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

## Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	
Туре	

Damage 2

Datte

Category

**Type** 



#### Extra VAUXHALL salvage check



CarCheck.co.uk

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 6/11



report date: 2024-03-29

## Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

# Owner history

e when mistery	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	
*************	
	More info >
Plate changes  See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	NK SIK
Flate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

## Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-06-30
Last registration	2024-02-06
Complete history	See info



Registration #1	2018-06-30	17 mi
Registration #2	2021-02-25	43.110 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



DS18HVX report date: 2024-03-29

# Safety ratings

NCAP rating	<b>大大大</b> 大大
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



# Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Kerb weight	1750 kg
Max. allowed weight	3030 kg

# Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M H4 - C158668LWZ

CarCheck.co.uk page 11/11