



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	BOXER HDI 333 L1H1 PROFESSIONAL P/V
Colour	White
Year of manufacture	2016
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.750 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	41.5 mpg
CO2 emission	180 g/km
CO2 label	I





**Internet history**

**Entry 1**

Date	2021-09-09
Pictures	3
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

MOT expiry date	2025-03-23
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	21
Total items failed	0

<b>MOT #8</b>	2024-03-22 08:30
MOT test number	490850601333
Result	✓ Passed
Next expiry date	2025-03-23

<b>MOT #7</b>	2023-03-20 08:12
MOT test number	113108883843
Result	✓ Passed
<b>Advice</b>	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

<b>MOT #6</b>	2022-03-08 09:50
MOT test number	839741492926
Result	✓ Passed

<b>MOT #5</b>	2021-03-24 13:10
MOT test number	116228605461
Result	✓ Passed

<b>MOT #4</b>	2021-03-11 09:39
MOT test number	993043900270
Result	✗ Failed
<b>MAJOR</b>	Electronic stability control warning lamp indicates a fault ASR traction control light on (7.12 (e))



<b>MOT #3</b>	2020-03-16 11:24
<b>MOT test number</b>	860770542227
<b>Result</b>	✓ Passed
<b>Minor</b>	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

<b>MOT #2</b>	2019-03-12 09:59
<b>MOT test number</b>	687104950514
<b>Result</b>	✓ Passed
<b>Advice</b>	Hand brake high
<b>Advice</b>	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords and worn outer wall (5.2.3 (d) (i))
<b>Advice</b>	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
<b>Advice</b>	Brake pedal wearing smooth (1.1.2 (c))
<b>Advice</b>	Offside wing mirror cover slight damage
<b>Advice</b>	Nearside Rear Nail in tyre



MOT #1 2019-02-15 09:31

MOT test number 976166815698

Result ✗ Failed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))

**MAJOR** Nearside Side repeater missing (4.4.1 (a) (ii))

**Advice** Nearside Rear Nail in tyre

**Advice** Brake pedal wearing smooth (1.1.2 (c))

**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** Offside wing mirror cover slight damage

**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MAJOR** Nearside Body component damaged and likely to cause injury wing mirror (6.2.1 (a) (i))

**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))

**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**Advice** Hand brake high

**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords and worn outer wall (5.2.3 (d) (i))



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 November 2024

✓  
**MOT**

**Expires:**  
23 March 2025

**Tax status** Valid until 1 November

**Days left** 186

**MOT expiry date** 23 March 2025

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>FG16GBZ</b>
Plate since	2019-09-29
Current registration	<b>FG16GBZ</b>
Plate since	2019-09-29

More info >



**Finance check**

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

<b>Finance company</b>	XXXXXXXX XX
<b>Date of agreement</b>	XXXXXXXX XX
<b>Agreement type</b>	XXXXXXXX XX
<b>Agreement term</b>	XXXXXXXX XX
<b>Agreement number</b>	XXXXXXXX XX
<b>Contact info</b>	XXXXXXXX XX

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-03-21
Last registration	2024-03-22
Complete history	<a href="#">See info</a>



Registration #1	2016-03-21	24 mi
Registration #2	2019-02-15	50.062 mi
Registration #3	2019-03-12	50.062 mi
Registration #4	2020-03-16	63.215 mi
Registration #5	2021-03-11	72.261 mi
Registration #6	2022-03-11	72.261 mi
Registration #7	2022-03-11	72.261 mi
Registration #8	2022-03-11	72.261 mi
Registration #9	2022-03-11	72.261 mi
Registration #10	2024-03-22	72.261 mi

[More info >](#)



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	<a href="#">see crash video</a>



Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJ90921684