






General information

Make	FIAT
Model	PANDA POP
Colour	Red
Year of manufacture	2016
Top speed	102 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С







2022-01-25
1
View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-04
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	26
Total items failed	3

MOT #8	2023-04-25 14:15
MOT test number	665536360422
Result	✓ Passed
Next expiry date	2024-05-04
Advice Nearside Play in steering rack inner joint(s)	
Advice Offside Rear Coil spring corroded @ base (5.3.1 (b) (i))	
Advice Nearside Rear Coil spring corroded @ base (5.3.1 (b) (i))	

MOT #7

MOT test	number
-----------------	--------

Result	🗙 Failed
Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))	
Advice Offside Rear Coil spring corroded @ base (5.3.1 (b) (i))	
Advice Nearside Play in steering rack inner joint(s)	
Advice Nearside Rear Coil spring corroded @ base (5.3.1 (b) (i))	
Advice Coolant level below minimum	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources	s (4.7.1
(b) (i))	

2023-04-25 10:18 449664120725





MOT #6	2022-05-05 07:27
MOT test number	923438518311
Result	✓ Passed
MOT #5	2022-01-28 13:35
MOT test number	514923354464
Result	✓ Passed
Advice Rear Both handbrake cables outer casings split.	
Advice Oil leak, but not excessive Oil sump slightly damp. (8.4.1 (a) (i))	
MOT #4	2021-03-02 16:30
MOT test number	430896271077
Result	✓ Passed
Advice Oil leak, but not excessive Oil sump slightly damp. (8.4.1 (a) (i))	

Auvice	On leak, but not excessive on sump slightly damp. (0.4.1 (d) (l))
Advice	Nearside Play in steering rack inner joint(s)
Advice	Front Exhaust mounting defective Bracket corroded away. (6.1.2 (a))
Advice	Both handbrake cables outer casings split.

MOT #3	2021-03-02 10:50
MOT test number	841632628617
Result	🗙 Failed
Advice Both handbrake cables outer casings split.	
Advice Front Exhaust mounting defective Bracket corroded away. (6.1.2 (a))	
Fail Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))	
Advice Nearside Play in steering rack inner joint(s)	
Advice Oil leak, but not excessive Oil sump slightly damp. (8.4.1 (a) (i))	
Fail Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))	





MOT #2		2020-03-02 11:12
MOT test	number	424464284790
Result		✓ Passed
Advice	Offside Brake cable damaged but not to excess (1.1.15 (a))	
Advice	Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Brake cable damaged but not to excess (1.1.15 (a))	
Advice	Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #1	2019-03-14 13:44
MOT test	number 545493342067
Result	✓ Passed
Advice	Front exhaust support clamp snapped
Advice	Front Tyre worn close to legal limit/worn on edge both front tyres worn on outer edges (5.2.3 (e))



Tax & MOT check

✓ Taxed Tax due: 1 May 2025	✓ MOT Expires: 4 May 2024
Tax status	Valid until 1 May
Days left	366
MOT expiry date	4 May 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Number of plates Carrent registration	
Rumber of plates Current registration Plate since	
Number of plates Current registration Flate since Current registration	
Number of plates Carrent registration Fals since Fals since	8000-20-20





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-03-24
Last registration	2023-04-25
Complete history	See info



Registration #1	2016-03-24	17 mi
Registration #2	2019-03-14	24.610 mi
Registration #3	2020-03-02	30.814 mi
Registration #4	2021-03-02	34.301 mi
Registration #5	2021-03-02	34.302 mi
Registration #6		11.177 esi
Registration #7		11.177 esi
Registration #8		11.117 esi
D 1 1 11 110		
Registration #9		11.777 esi

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1882 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg
Additional information	
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number Carcheck.co.uk	1523903 page 12/12