





### General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Purple
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	А







## Internet history

Entry 1	
Date	2021-09-03
Pictures	26
Listing price	View report









source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-09
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	14
Total items failed	8

MOT #12		2024-03-05 09:24
MOT test	number	835251367440
Result		✓ Passed
Next expi	ry date	2025-03-09
Advice	Rear Exhaust mounting defective both (6.1.2 (a))	
Advice (i)) Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a)		
Advice	Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice Corrosion to rear.		
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords	5 (5.2.3 (d) (i))

MOT #11		2023-03-07 15:15
MOT test	number	966406218291
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	





MOT #10	2023-03-07 12:00
MOT test number	350071643339
Result	🗙 Failed
FailNearside Windscreen washer jets misaligned and not providing sufficient fluid to th(a))	ne windscreen (3.5
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
<b>Fail</b> Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
FailOffside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
FailOffside Windscreen washer jets misaligned and not providing sufficient fluid to the (a))	windscreen (3.5
Advice Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	
Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #9	2022-03-01 18:06
MOT test number	801173838665
Result	✓ Passed
MOT #8	2021-02-15 11:26

MOT test number	114005984075
Result	✓ Passed

MOT #7	2020-03-10 10:20
MOT test number	954139959707
Result	✓ Passed





MOT #6		2020-03-10 10:20
MOT test number		150754401980
Result		× Failed
Pass with rectification Ne	arside Front Direction indicator not working (4.4.1 (a) (ii))	
MOT #5		2019-02-28 15:32
MOT test number		454843477846
Result		✓ Passed
MOT #4		2018-03-08 10:17
MOT test number		910290146624
Result		✓ Passed
MOT #3		2017-02-23 13:58
MOT test number		711964013066
Result		✓ Passed
MOT #2		2016-03-02 14:30
MOT test number		262170560423
Result		✓ Passed
MOT #1		2016-03-02 10:45
MOT test number		776603691429
Result		× Failed
Advice Offside Front Tyre w	orn close to the legal limit (4.1.E.1)	
Fail Nearside Front Tyre treated	ad depth below requirements of 1.6mm (4.1.E.1)	



Tax & MOT check

✓ Taxed	√ МОТ
1 November 2024	<b>Expires:</b> 9 March 2025
Tax status	Valid until 1 November
Days left	186
MOT expiry date	9 March 2025
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48
Band	٨

Band	А
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable





#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
*******	
******	
**********	
*******	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-08
Last registration	2024-03-05
Complete history	See info



Registration #1	2013-03-08	29 mi
Registration #2	2016-03-02	17.476 mi
Registration #3	2016-03-02	17.476 mi
Registration #4	2017-02-23	21.719 mi
Registration #5	2018-03-08	25.311 mi
Registration #6	2019-02-28	28.483 mi
Registration #7	2020-03-10	30.928 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		10.300 est
Registration #12		01.000 est
Registration #12 Registration #13		0.000 est 0.000 est





### Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
\$0566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight	
Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg
Additional information	
Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12