





### General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	White
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	113 BHP
Max. torque	145 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	С





Internet history			
Entry 1			
Date	2022-05-10	)	
Pictures	6		
Listing price	View repor	t	
NEW ARRIVAL Integes Coming Soon.	AA You're in safe hands This dealer has signed our Dealer Promise	AA You're in safe hands This dealer has signed our Dealer Promise	

source: cargurus.co.uk



# MOT history

MOT expiry date	2025-05-09
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #13	2024-04-23 13:56
MOT test number	108719142674
Result	✓ Passed
Next expiry date	2025-05-09

MOT #12	2023-04-11 14:58
MOT test number	545022570877
Result	✓ Passed

MOT #11	2022-05-10 15:09
MOT test number	569737738777
Result	✓ Passed

MOT #10	2021-09-06 12:54
MOT test number	206295874218
Result	✓ Passed

МОТ #9	2020-08-31 15:09
MOT test number	894879666414
Result	✓ Passed



664466704540



MOT #8	2019-08-28 15:26
MOT test number	632373922210
Result	✓ Passed
MOT #7	2018-08-29 15:33
MOT test number	937086430220
Result	✓ Passed
МОТ #6	2018-04-13 09:51
MOT test number	872042179703
Result	✓ Passed
MOT #5	2017-03-29 14:15

### MOT test number

Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #4		2017-03-29 10:43
MOT test	number	597908995876
Result		🗙 Failed
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.	5.1i)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (	3.5.1i)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
<b>Fail</b> Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)		





MOT #3	2016-04-09 0	8:43
MOT test number	706990678	8398
Result	🗸 Pa	ssed
MOT #2	2015-04-23 0	9:47
MOT test number	257213715	5184
Result	🗸 Pa	ssed
Advice Rear brake disc worn	pitted or scored, but not seriously weakened (3.5.1i)	
<b>Notice</b> Nsr tyre approachin g	limit markers	
MOT #1	2014-04-19 1	.2:35
MOT test number	936639304	4142
Result	🗸 Pa	ssed



Tax & MOT check

	√ Taxed		✓ МОТ
<b>Tax due:</b> 1 May 2025		<b>Expires:</b> 9 May 2025	
Tax status			Valid until 1 May
Days left			366
MOT expiry date			9 May 2025
Full MOT history			See MOT history
Tax calculation			
Vehicle class		59	

venicle class	29
Band	С
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-





#### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Law P
Туре	
Damage 2	AMPLE
Damage 2	E CAT D
Date	 *
Category	 AMPT
Туре	

#### Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 =

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	
************	
********	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this HONDA had different number plat	es.
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-04-22
Last registration	2024-04-23
Complete history	See info



Registration #1	2011-04-22	17 mi
Registration #2	2014-04-19	39.665 mi
Registration #3	2015-04-23	52.296 mi
Registration #4	2016-04-09	64.347 mi
Registration #5	2017-03-29	76.096 mi
Registration #6	2017-03-29	76.096 mi
Registration #7	2018-04-13	82.640 mi
Registration #8	2018-08-29	85.124 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.117 esi

More info  $\rightarrow$ 





# Safety ratings

NCAP rating	****
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	<u>see crash video</u>



Dimensions & weight	
Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg
Additional information	
Fuel tank capacity	40 I
	40 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 3