





report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 URBAN
Colour	Silver
Year of manufacture	2009
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-28


Internet history

Entry 1

Date 2021-06-08

Pictures 21

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-08-17
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #13		2023-08-07 11:58
MOT test	number	814501817083
Result		✓ Passed
Next expi	ry date	2024-08-17
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	ı
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2022-08-09 11:49
MOT test number	547372306847
Result	✓ Passed
MOT #11	2021-07-20 12:51
MOTILIA	E3E344304313

1101 # 22	2021 07 20 12.31
MOT test number	535344384313
Result	✓ Passed

MOT #10	2021-07-19 14:59
MOT test number	211464056100
Result	X Failed
Advice Front Brake disc worn, pitted or scored, but not seriously weaker Fail Horn not working (7.7 (a) (ii))	ned (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



MOT #9

MW09XLK

report date: 2024-03-28

2020-07-20 10:33

MOT test number 140845029467

Result ✓ Passed

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both bushes splitting/cracking (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened also front brake pads wearing low (1.1.14 (a) (ii))

MOT #8 2019-08-15 11:39

MOT test number 881623613046

Result ✓ Passed

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #7 2018-08-09 11:04

MOT test number 681241289005

MOT #6 2017-08-09 09:46

MOT test number 387074821457

Result ✓ Passed

MOT #5 2016-08-10 15:33

MOT test number 598379918740

Result
✓ Passed

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #4 2015-08-17 14:47

MOT test number 282487101739

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3	2014-08-18 15:30
MOT test number	365140534292
Result	✓ Passed
MOT #2	2013-08-14 16:35
MOT test number	395116423417
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1	E.1)
Advice Offside Front Tyre worn close to the legal limit (4.1.E	E.1)

MOT #1	2012-08-14 15:54
MOT test number	599127822209
Result	✓ Passed
Notice N/S/R tyre cracking between tread	
Notice O/S/R tyre cracking between tread	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	17 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

\sim		histor	
- () ()	vnor	nictoi	↷

For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full	

THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	NIE NIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-08-17
Last registration	2023-08-07
Complete history	See info



Registration #1	2009-08-17	19 mi
Registration #2	2012-08-14	10.600 mi
Registration #3	2013-08-14	13.235 mi
Registration #4	2014-08-18	17.097 mi
Registration #5	2015-08-17	19.596 mi
Registration #6	2016-08-10	21.330 mi
Registration #7	2017-08-09	24.720 mi
Registration #8	2018-08-09	26.998 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		91,700 esi
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	875 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine number6276979