





report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER SPORT SDV6 HSE
Colour	Black
Year of manufacture	2017
Top speed	130 mph
0 - 100 km/h	7.2 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	225 kW / 306 HP / 306 BHP
Max. torque	700 Nm at 1.500 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	44.1 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-10-07

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-09-23
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-21
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	10
Total items failed	4

MOT #5		2024-01-22 08:54
MOT test	number	305638643763
Result		✓ Passed
Next exp	iry date	2025-01-21
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Plastic cover fitted top of the engine and under the floor	
Advice Rear Inner Tyre worn close to legal limit/worn on edge both sides rear inner edges (5.2.3 (e))		
Advice Nearside Front tyre wearing and getting low to nearing 2mm		
Minor Offside Front Lower Anti-roll bar ball joint dust cover severely deteriorated ball joint dust cover (5.3.4 (b) (i))		

MOT #4		2023-01-11 09:12
MOT test	number	967573589313
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge both sides front (5.2.3 (e))	
Advice	Plastic cover fitted top of the and under the floor	

MOT #3	2021-09-10 10:30
MOT test number	322634821441
Result	✓ Passed

CarCheck.co.uk page 3/11



AE67VZL

report date: 2024-03-28

MOT #2 2021-09-07 08:42 595285487692 **MOT** test number Result **★** Failed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Advice Offside Rear Nail in tyre Advice Oil leak, but not excessive driver side engine bay (8.4.1 (a) (i)) Offside Rear Tyre has ply or cords exposed open cut (5.2.3 (d) (ii)) Fail Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Nearside Rear Tyre has ply or cords exposed open cut (5.2.3 (d) (ii)) Fail

MOT #1	2020-08-27 16:11
MOT test number	656442750456
Result	√ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation

-	
Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history


Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	

Damage 2

Damage 2	
Date	
Category	



Extra LAND ROVER salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many of ROVER have? Check it in the premium report and see all owner registrations. Download	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	AIN UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-08
Last registration	2024-01-22
Complete history	See info



Registration #1	2017-09-08	24 mi
Registration #2	2020-08-27	40.132 mi
Registration #3	2021-09-07	50.729 mi
Registration #4	2021-09-10	50.749 mi
Registration #5		91,777 esi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

More info >

page 10/11 CarCheck.co.uk



Safety ratings

NCAP rating	****
Adult	91%
Children	84%
Pedestrian	63%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	2220 mm
Height	1801 mm
Length	4856 mm
Wheel base	2923 mm
Kerb weight	2115 kg
Max. allowed weight	3050 kg

Additional information

Fuel tank capacity	89 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1085520306DT

CarCheck.co.uk page 11/11