





report date: 2024-03-28

General information

Make	LEXUS
Model	IS 300H F SPORT
Colour	Grey
Year of manufacture	2014
Top speed	125 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	220 BHP
Max. torque	221 Nm at 4.200 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	60.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date	2022-01-11
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT	history
1.101	iliocol y

MOT expiry date	2024-08-02
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	1
Total items failed	0

MOT #7	2023-07-25 09:39
MOT test number	163751091186
Result	✓ Passed
Next expiry date	2024-08-02
Advice Offside Front Brakes imbalanced requirements only just met. It woul system requires adjustment or repair. (1.2.1 (b) (i))	ld appear that the braking

MOT #6	2022-08-03 09:55
MOT test number	796947685931
Result	✓ Passed
MOT #5	2021-11-12 13:57
MOT test number	425581930597
Result	✓ Passed
MOT #4	2020-11-19 14:29
MOT test number	453509954776
Result	✓ Passed

MOT #3	2019-11-25 14:10
MOT test number	921253670517
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2	2018-11-19 13:37
MOT test number	559845757285
Result	✓ Passed
MOT #1	2017-11-21 14:14
MOT test number	338054506170

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	В
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners of have? Check it in the premium report and see all owner registrations. Download the full re	
manage of the same	

	More info >
Plate changes	
See in this check if this LEXUS had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LEXUS is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-11-28
Last registration	2023-07-25
Complete history	See info



Registration #1	2014-11-28	16 mi
Registration #2	2017-11-21	11.184 mi
Registration #3	2018-11-19	13.875 mi
Registration #4	2019-11-25	16.857 mi
Registration #5	2020-11-19	18.990 mi
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1430 mm
Length	4665 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number 2AR1060928