



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Red
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg



LABEL UNKNOWN

**MOT history**

MOT #13	2022-11-04 21:31
MOT test number	114310693253
Result	✓ Passed
Next expiry date	2023-11-03
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #12	2021-04-14 13:43
MOT test number	418185302918
Result	✗ Failed
Fail	Offside Headlamp aim too high (4.1.2 (a))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #11	2020-03-19 17:45
MOT test number	244409726507
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Service brake fluctuating, but not excessively on limit (1.2.1 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nsf head light slightly insecure / long foot brake travel

**MOT #10**

2019-03-04 18:17

MOT test number

411505535076

Result

✓ Passed

- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Poor pattern head light secured with big screw
- Advice** Items removed from driver's view prior to test
- Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Smells of burning oil no blue smoke

MOT #9

2019-02-28 16:53

MOT test number

421402429109

Result

✗ Failed

- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Nearside Headlamp aim too high (4.1.2 (a))
- Minor** Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Fail** Emissions not tested excessive blue smoke (8.2.1.2 (d))
- Advice** Items removed from driver's view prior to test

MOT #8

2018-03-01 13:28

MOT test number

638918360912

Result

✓ Passed

- Advice** Osr light insecure / long foot brake travel
- Advice** Rear Tyre worn close to the legal limit rear tyres worn (4.1.E.1)

**MOT #7** 2017-02-27 17:54**MOT test number** 278965103773**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2016-02-24 10:55**MOT test number** 690298424835**Result** ✓ Passed**Advice** Minor oil leak from filter**Advice** Kids seat fitted nsr, seatbelt not checked**Advice** Airbox pipe insecure**Advice** 2x nails in nsr tyre**Advice** Both wipers slightly worn**MOT #5** 2015-02-27 09:56**MOT test number** 436688555015**Result** ✓ Passed**Notice** Nsr seat belt not checked due to child seat**Notice** Nsr alloy buckeled / osr steel**MOT #4** 2014-02-01 13:04**MOT test number** 388702534031**Result** ✓ Passed**Notice** Steel wheel fitted osr**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #3** 2014-02-01 10:46**MOT test number** 107462534000**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Notice** Nail nsr tyre**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Both front tyres on the limit**Notice** Steel wheel fitted osr**MOT #2** 2012-09-04 16:49**MOT test number** 986968742283**Result** ✓ Passed**Notice** Nsr seat belt removed /nsf seat belt not inspected due to child seat**MOT #1** 2011-04-11 16:41**MOT test number** 375371901185**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-03-31
Last registration	2022-11-04
Complete history	See info



Registration #1	2008-03-31	15 mi
Registration #2	2011-04-11	17.990 mi
Registration #3	2012-09-04	27.190 mi
Registration #4	2014-02-01	33.988 mi
Registration #5	2014-02-01	33.988 mi
Registration #6	2015-02-27	40.482 mi
Registration #7	2016-02-24	46.337 mi
Registration #8	2016-02-24	46.337 mi
Registration #9	2016-02-24	46.337 mi
Registration #10	2016-02-24	46.337 mi
Registration #11	2016-02-24	46.337 mi
Registration #12	2016-02-24	46.337 mi
Registration #13	2016-02-24	46.337 mi
Registration #14	2016-02-24	46.337 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1314 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BFS 062931