





report date: 2024-03-28

### General information

Make	FORD
Model	KA STUDIO
Colour	Black
Year of manufacture	2008
Top speed	104 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	68 BHP
Max. torque	106 Nm at 3.000 rpm
Engine capacity	1.299 сс
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg
CO2 emission	141 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

#### Entry 1

Date	2021-06-15
Pictures	1
Listing price	<u>View report</u>



source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

## MOT history

MOT expiry date	2024-07-20
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	15
Total items failed	2

MOT #15	5	2023-07-19 11:11
MOT test	t number	434057330078
Result		✓ Passed
Next exp	piry date	2024-07-20
Advice (b))	Offside Front Headlamp has a product on the lens but not seriously reducing lig	ht output (4.1.4
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))		
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive	movement (5.3.4
Minor	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b)	(i))

MOT #14		2022-07-21 09:48
MOT test number		409264396661
Result		<b>✓</b> Passed
MOT #13		2022-07-21 09:48
MOT test number		610674611183
Result		<b>X</b> Failed
Pass with rectification	Nearside Headlamp aim too far to the left (4.1.2 (a))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2021-06-21 13:46

**MOT test number** 937782564128

**Result** ✓ Passed

**MOT #11** 2021-06-17 12:39

**MOT test number** 869733285920

**Result** X Failed

**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength seal (5.3.6 (a) (i))

**MOT #10** 2020-07-13 13:26

**MOT test number** 680091590932

Result \rightarrow Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Items removed from driver's view prior to test

**Advice** Offside Rear Inner and outre sill slightly corroded.

MOT #9 2019-07-03 13:38

MOT test number 634045205377

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Rear Outer Sill slight corrosion .

MOT #8 2018-07-27 13:41

MOT test number 871285244597

Result 

Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7 2017-07-13 10:24

**MOT test number** 341471277602

Result \( \sqrt{Passed} \)

**Advice** Front and rear wipers smearing slightly

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #6 2016-07-27 11:11

MOT test number 602396864055

Result \( \sqrt{Passed} \)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #5 2015-07-13 12:18

**MOT test number** 998624995115

**MOT #4** 2014-07-14 10:20

MOT test number 619325894113

**Result** ✓ Passed

MOT #3 2013-07-15 10:53

**MOT test number** 437986293166

Result \( \sqrt{Passed} \)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2012-07-27 11:26

MOT test number 806379702240

**Result** 
✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

**MOT #1** 2011-07-29 14:08

**MOT test number** 686760311295

**Result** ✓ Passed

Advice

Nearside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 6/13



BK58WML report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	20 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Venicle class	40
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

# Owner history

Owner mistory	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
********	
***************************************	
********	
*************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	AK WAR
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-30
Last registration	2023-07-19
Complete history	See info



Registration #1	2008-09-30	22 mi
Registration #2	2011-07-29	13.252 mi
Registration #3	2012-07-27	17.782 mi
Registration #4	2013-07-15	20.319 mi
Registration #5	2014-07-14	24.081 mi
Registration #6	2015-07-13	27.928 mi
Registration #7	2016-07-27	31.546 mi
Registration #8	2017-07-13	34.490 mi
Registration #9	2018-07-27	35.706 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es

More info >

CarCheck.co.uk page 12/13



BK58WML report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1827 mm
Height	1413 mm
Length	3620 mm
Wheel base	2448 mm
Kerb weight	898 kg
Max. allowed weight	1265 kg

## Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles2Engine number8D04490