





report date: 2024-03-28

General information

Make	AUDI
Model	S3 S3 TFSI QUATTRO
Colour	Blue
Year of manufacture	2008
Top speed	155 mph
0 - 60 mph	5.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	265 BHP
Max. torque	350 Nm at 2.500 rpm
Engine capacity	1.984 сс
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	39.2 mpg
Consumption combined	31.0 mpg
CO2 emission	217 g/km
CO2 label	K



CarCheck.co.uk page 1/15



Internet history

Entry 1

Date	2021-06-28	
Pictures	1	
Listing price	View report	



source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2025-01-15
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	25
Total items failed	13

MOT #20	2024-01-06 12:53
MOT test number	168286235083
Result	✓ Passed
Next expiry date	2025-01-15

MOT #19		2024-01-06 12:53
MOT test number		993244281491
Result		X Failed
Pass with rectification	Rear fog lamp not working (4.5.1 (a) (ii))	

MOT #18		2023-01-16 12:28
MOT test	number	601061065465
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/15



MOT #17

FY08VZS report date: 2024-03-28

2023-01-16 12:28

MOT test number 200514265939

Result × Failed

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Nearside Front Windscreen wiper not working (3.4 (a))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16 2021-12-18 16:59

MOT test number 194840733991

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Coil spring corroded Both front and offside rear (5.3.1 (b) (i))

CarCheck.co.uk page 4/15



MOT #15 2021-12-15 16:34

MOT test number 621597570516

Result X Failed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Headlamp levelling device inoperative (4.1.5 (a))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail Offside Rear Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #14 2020-12-17 12:24

MOT test number 303413041788

Result

Passed

Advice All 4 coil springs corroded and worn but not broken

Advice Slight under body corrosion

MOT #13 2019-06-20 09:53

MOT test number 467374891133

Result ✓ Passed

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

CarCheck.co.uk page 5/15



Result

Fail

FY08VZS report date: 2024-03-28

Passed

MOT #12 2018-11-13 11:12

MOT test number 968026906606

Result \rightarrow Passed

Advice Under covers fitted unable to see some parts.

MOT #11 2017-11-13 18:01

MOT test number 394147838623

Advice Under covers fitted unable to see some parts.

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #10 2017-11-13 11:07

MOT test number 607462766868

Result X Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)

Fail Offside Front coil spring broken (2.4.C.1a)

Advice Under covers fitted unable to see some parts.

MOT #9 2016-12-05 14:32

MOT test number 315927106109

Result
✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

MOT #8 2016-03-09 13:08

MOT test number 905380677641

Result

Passed

CarCheck.co.uk page 6/15



MOT #7

FY08VZS report date: 2024-03-28

2016-03-08 10:57

MOT test number 388820616149

Result × Failed

Fail Offside Registration plate lamp not working (1.1.C.1d)

Fail Nearside Front coil spring broken (2.4.C.1a)

MOT #6 2015-02-27 16:53

MOT test number 165778055037

Result ✓ Passed

MOT #5 2014-03-14 16:56

MOT test number 779323874000

Result \(\sqrt{Passed} \)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #4 2014-03-14 14:42

MOT test number 125853274454

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #3 2013-03-22 15:18

MOT test number 948411483055

Result ✓ Passed

MOT #2 2012-02-29 15:15

MOT test number 126350362080

Result

Passed

CarCheck.co.uk page 7/15



MOT #1 2011-03-18 15:04

MOT test number 255237871057

Result ✓ Passed

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 May
Days left	368
MOT expiry date	15 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

e when motorly		
For how long did the current and previous owner(s) have this AUDI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>have</u>		ve?

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		,
Current registration	NK NY	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 12/15



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-03-19
Last registration	2024-01-06
Complete history	See info



Registration #1	2008-03-19	8 mi
Registration #2	2011-03-18	38.542 mi
Registration #3	2012-02-29	50.488 mi
Registration #4	2013-03-22	59.888 mi
Registration #5	2014-03-14	67.542 mi
Registration #6	2014-03-14	67.543 mi
Registration #7	2015-02-27	78.693 mi
Registration #8	2016-03-08	83.709 mi
Registration #9	2016-03-09	83.709 mi
Registration #10	2016-12-05	88.594 mi
Registration #11	2017-11-13	101.106 mi
Registration #12		11.777 es
Registration #13		11.777 mi
Registration #14		0.00 44
Registration #15		11.777 mi
Registration #16		11.777 es
Registration #17		11.777 mi
Registration #18		11.777 es
Registration #19		11.777 ms
Registration #20		11.777 es
Registration #21		11.777 mi
Registration #22		11.77 m

More info >

CarCheck.co.uk page 14/15



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1399 mm
Length	4214 mm
Wheel base	2578 mm
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles CarCheck.co.uk	2 page 15/15

Engine number

BHZ 010999