



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 CDTI CREWVAN
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	240 Nm at 2.300 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-12-22
Pictures	16
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-03
Pictures	1
Listing price	View report



source: [cargurus.co.uk](#)

**MOT history**

MOT #14	2021-10-07 13:33
MOT test number	693461611591
Result	✓ Passed
Next expiry date	2022-10-06
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view small chip (3.2 (a) (i))
Advice	Front Play in steering rack inner joint(s) x2
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2020-12-02 17:22
MOT test number	690448453298
Result	✓ Passed
Advice	Play in steering rack inner joint(s)
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #12	2020-12-02 17:22
MOT test number	821536904318
Result	✗ Failed
Pass with rectification	Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
Advice	Play in steering rack inner joint(s)
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #11**

2019-03-22 16:28

MOT test number

605749981986

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2019-03-19 08:22

MOT test number

915907959141

Result

✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a))
- Fail** Brake pedal anti-slip provision missing (1.1.2 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

2018-03-01 15:40

MOT test number

908366374226

Result

✓ Passed

**MOT #8** 2018-03-01 15:40**MOT test number** 364429118147**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #7** 2017-03-03 16:36**MOT test number** 141772850337**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2017-02-10 14:55**MOT test number** 234387071199**Result** ✗ Failed**Pass with rectification** Registration plate lamp not illuminating the registration plate (1.1.C.1e)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Horn not working (1.6.2a)**Fail** Battery insecure (1.9.1)**MOT #5** 2015-09-10 14:01**MOT test number** 717638565314**Result** ✓ Passed

**MOT #4** 2015-09-05 12:40**MOT test number** 778728422247**Result** ✗ Failed

Fail Offside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt Link arm bush. (2.4.G.2)

Fail Nearside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt Link arm bush. (2.4.G.2)

MOT #3 2014-10-01 17:24**MOT test number** 628774474265**Result** ✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2014-10-01 17:24**MOT test number** 555984974279**Result** ✗ Failed

Pass with rectification Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1 2013-09-12 16:30**MOT test number** 266785753223**Result** ✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	VAUXHALL
Plate since	2024-03-29
Current registration	VAUXHALL
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-30
Last registration	2021-10-07
Complete history	See info



Registration #1	2010-09-30	17 mi
Registration #2	2013-09-12	44.330 mi
Registration #3	2014-10-01	77.907 mi
Registration #4	2015-09-05	94.344 mi
Registration #5	2015-09-10	94.345 mi
Registration #6	2017-02-10	108.922 mi
Registration #7	2017-03-03	108.922 mi
Registration #8	2018-03-01	130.474 mi
Registration #9	2019-05-20	151.277 mi
Registration #10	2019-05-20	151.277 mi
Registration #11	2019-05-20	151.277 mi
Registration #12	2019-05-20	151.277 mi
Registration #13	2019-05-20	151.277 mi
Registration #14	2019-05-20	151.277 mi
Registration #15	2019-05-20	151.277 mi
Registration #16	2021-10-07	171.277 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1329 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Engine number	2086685