





report date: 2024-03-29

General information

Make	FIAT
Model	TIPO EASY
Colour	Grey
Year of manufacture	2018
Top speed	115 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date	2021-06-21	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/12



HF18WEX
report date: 2024-03-29

MOT history

MOT expiry date	2025-03-07
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	22
Total items failed	3

MOT #6		2024-02-26 15:57
MOT test	number	657861815463
Result		✓ Passed
Next expiry date 2025-03-07		2025-03-07
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

MOT #5		2024-02-26 10:00
MOT test	number	728792354416
Result		× Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Nearside Rear Nail in tyre

Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt

Offside Rear Nail in tyre

MOT #3			2023-02-24 10:19
MOT test	number		564409554688
Result			X Failed
Advice	Nearside Rear N	ail in tyre	
Pass wit	h rectification	Offside Front Windscreen washer provides insufficient v	washer liquid (3.5 (a))
MAJOR	Offside Front Wi	ndscreen wiper does not clear the windscreen effectively	(3.4 (b) (ii))
MAJOR	Nearside Rear S	hock absorbers has a serious fluid leak (5.3.2 (b))	
Advice	Offside Rear Chi	ld Seat fitted not allowing full inspection of adult belt	
Pass wit	h rectification	Nearside Front Windscreen washer provides insufficient	t washer liquid (3.5 (a))
Advice	Offside Rear Nai	l in tyre	
MAJOR	Nearside Front V	Vindscreen wiper does not clear the windscreen effective	ely (3.4 (b) (ii))
Pass wit	h rectification	Offside Front Headlamp aim too high (4.1.2 (a))	
MAJOR	Offside Front Co	il spring fractured or broken (5.3.1 (b) (i))	
Advice	Nearside Rear C	hild Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #1	2021-03-05 11:46
MOT test number	255624595023
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	7 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra FIAT salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

$\hat{}$	
()Whor	hictory
OWILL	11151 OT V
Owner	,

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report	

HARMAN CO.	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK ZIS
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-03-08
Last registration	2024-02-26
Complete history	See info



Registration #1	2018-03-08	14 mi
Registration #2	2021-03-05	11.131 mi
Registration #3		11.777 es
Registration #4	2022-03-02	20.234 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1792 mm
Height	1514 mm
Length	4571 mm
Wheel base	2638 mm
Kerb weight	1280 kg
Max. allowed weight	1755 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12