





report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 POWERPULSE R-DESIGN PRO AWD
Colour	Red
Year of manufacture	2018
Top speed	137 mph
0 - 60 mph	7.4 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	480 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	52.3 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date	2022-01-05
Pictures	1
Listing price	View report



source: autoonline.co.uk

Entry 1

Date	2021-10-08
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2025-04-18
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	7
Total items failed	2

MOT #7	2024-04-19 13:35
MOT test number	697296184484
Result	✓ Passed
Next expiry date	2025-04-18
Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6	2023-10-05 16:05
MOT test number	515306631912
Result	✓ Passed
MOT #5	2023-10-05 10:50
MOT test number	146473811072
Result	× Failed

MOT #4		2022-10-13 10:17
MOT test	number	890898303426
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

267679799929

Result

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2	2021-10-29 13:57
MOT test number	780816287599
Result	✓ Passed
MOT #1	2021-02-26 12:02
MOT test number	694825849386
Result	✓ Passed

CarCheck.co.uk page 4/11



CN18XUM report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

O		biote	- 100
· Ow	ne e	histo	иν

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
MARKET STATE OF THE STATE OF TH	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	OK ON THE PROPERTY OF THE PROP
Plate since	
Current registration	RAIN NE.
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



CN18XUM report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-03-01
Last registration	2024-04-19
Complete history	See info



Registration #1	2018-03-01	14 mi
Registration #2	2021-02-26	17.444 mi
Registration #3		D.707 es
Registration #4	2021-10-29	20.680 mi
Registration #5		D.707 es
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		77,777 46
Registration #9		D.707 es
Registration #10		11.177 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
S0569	

Safety ratings

NCAP rating	****
Adult	97%
Children	87%
Pedestrian	72%
Safety systems	94%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2008 mm
Height	1776 mm
Length	4950 mm
Wheel base	2984 mm
Kerb weight	2009 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	71
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/1:

Number of axles 2

Engine number 2326691