



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	C C180K SE
Colour	Black
Year of manufacture	2005
Top speed	137 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	220 Nm at 2.500 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	33.6 mpg
CO2 emission	203 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-06-15
Pictures	43
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-13
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	17
Total items failed	9

MOT #21	2023-06-13 10:28
MOT test number	442288099969
Result	✓ Passed
Next expiry date	2024-06-13

MOT #20	2022-06-14 13:01
MOT test number	521020087249
Result	✓ Passed
Advice	Offside Front Track rod end ball joint has slight play Inner Rack arm (2.1.3 (b) (i))

MOT #19	2022-06-13 11:43
MOT test number	701106673867
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm Worn in middle. (5.2.3 (e))
Advice	Offside Front Track rod end ball joint has slight play Inner Rack arm (2.1.3 (b) (i))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm Worn in middle. (5.2.3 (e))
Fail	Nearside Front Lower Suspension arm ball joint excessively worn As Marked. (5.3.4 (a) (i))

MOT #18	2021-06-14 09:25
MOT test number	653292276367
Result	✓ Passed

**MOT #17** 2020-10-14 07:40**MOT test number** 904373030005**Result** ✓ Passed**MOT #16** 2020-10-13 09:57**MOT test number** 456728181215**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #15** 2019-09-12 07:11**MOT test number** 791964968762**Result** ✓ Passed**MOT #14** 2019-09-11 12:25**MOT test number** 281516521708**Result** ✗ Failed**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13** 2018-08-23 15:13**MOT test number** 637136839121**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12** 2018-08-23 10:32**MOT test number** 567871586405**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Headlamp levelling device inoperative (4.1.5 (a))**MOT #11** 2017-09-07 13:36**MOT test number** 532983051255**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2017-09-07 09:00**MOT test number** 205583781740**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #9** 2016-08-16 09:13**MOT test number** 845886325429**Result** ✓ Passed**MOT #8** 2015-09-09 16:36**MOT test number** 410683860972**Result** ✓ Passed

**MOT #7** 2014-09-09 09:51**MOT test number** 169312154200**Result** ✓ Passed**MOT #6** 2013-09-09 09:12**MOT test number** 686732453228**Result** ✓ Passed**MOT #5** 2012-08-29 16:27**MOT test number** 228242142201**Result** ✓ Passed**MOT #4** 2011-08-05 10:29**MOT test number** 746867111216**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-08-13 09:16**MOT test number** 944525520284**Result** ✓ Passed**Notice** Both front inner tyre side walls have slight cracking to them**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in tread of n/s/rear tyre**Advice** Offside Outer Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2009-08-20 11:41
MOT test number	551342239260
Result	✓ Passed

MOT #1	2008-08-28 11:44
MOT test number	923381348216
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
13 June 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	13 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 YJ55HXH
Plate since	2019-06-29
Current registration	 YJ55HXH
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-09-03
Last registration	2023-06-13
Complete history	See info



Registration #1	2005-09-03	13 mi
Registration #2	2008-08-28	10.486 mi
Registration #3	2009-08-20	14.136 mi
Registration #4	2010-08-13	19.829 mi
Registration #5	2011-08-05	25.958 mi
Registration #6	2012-08-29	30.661 mi
Registration #7	2013-09-09	35.707 mi
Registration #8	2014-09-09	42.403 mi
Registration #9	2015-09-09	46.609 mi
Registration #10	2016-08-16	49.745 mi
Registration #11	2017-09-07	53.535 mi
Registration #12	2017-09-07	53.535 mi
Registration #13	2018-09-07	57.325 mi
Registration #14	2019-09-07	61.115 mi
Registration #15	2020-09-07	64.905 mi
Registration #16	2021-09-07	68.695 mi
Registration #17	2022-09-07	72.485 mi
Registration #18	2023-06-13	76.275 mi
Registration #19	2023-06-13	76.275 mi
Registration #20	2023-06-13	76.275 mi
Registration #21	2023-06-13	76.275 mi
Registration #22	2023-06-13	76.275 mi
Registration #23	2023-06-13	76.275 mi

More info >



Dimensions & weight

Width	1957 mm
Height	1406 mm
Length	4343 mm
Wheel base	2715 mm
Kerb weight	1465 kg
Max. allowed weight	1935 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	27194630543695