



report date: 2024-03-29

General information

Make	FORD
Model	FIESTA EDGE
Colour	Silver
Year of manufacture	2010
Top speed	104 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm at 4.200 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	133 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-09-05
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	27
Total items failed	23

MOT #17	2023-09-05 13:22
MOT test number	287793228899
Result	✓ Passed
Next expiry date	2024-09-05
Advice	Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn bothsides (5.1.2 (b) (i))
Advice	Rear Coil spring corroded bothsides (5.3.1 (b) (i))
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material bothsides (1.1.11 (c))

**MOT #16**

2023-09-02 12:24

MOT test number

772121386768

Result**✗ Failed**

- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn bothsides (5.1.2 (b) (i))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Rear Coil spring corroded bothsides (5.3.1 (b) (i))
- Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material bothsides (1.1.11 (c))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Front Steering linkage ball joint has excessive play rack end (2.1.3 (b) (i))
- Fail** Offside Rear Exhaust shield missing where fitted as original equipment creating a risk of fire (6.1.3 (e))

MOT #15

2022-09-01 13:54

MOT test number

359090282035

Result**✓ Passed**

- Advice** Rear Coil spring corroded bothsides (5.3.1 (b) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge bothsides (5.2.3 (e))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement bothsides (5.3.4 (a) (i))
- Advice** Front Brake hose has slight corrosion to ferrule bothsides (1.1.12 (f) (i))
- Advice** Nearside Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #14**

2022-09-01 10:12

MOT test number

147165218568

Result

✗ Failed

- Fail** Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement bothsides (5.3.4 (a) (i))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Headlamp aim not tested (4.1.2 (b))
- Advice** Rear Coil spring corroded bothsides (5.3.1 (b) (i))
- Advice** Front Brake hose has slight corrosion to ferrule bothsides (1.1.12 (f) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))
- Advice** Rear Tyre worn close to legal limit/worn on edge bothsides (5.2.3 (e))
- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #13

2021-08-28 11:16

MOT test number

536888112020

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2020-09-03 12:27

MOT test number

260513074866

Result

✓ Passed

**MOT #11** 2020-09-02 10:02**MOT test number** 416312528381**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #10** 2019-08-30 16:34**MOT test number** 362655462445**Result** ✓ Passed**Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-09-06 08:08**MOT test number** 804241699410**Result** ✓ Passed**MOT #8** 2018-09-04 12:01**MOT test number** 427012529796**Result** ✗ Failed**Fail** Registration plate incorrect front and rear (0.1 (c))**Fail** Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**MOT #7** 2017-08-30 15:23**MOT test number** 310099254858**Result** ✓ Passed

**MOT #6** 2017-08-30 10:47**MOT test number** 374827807345**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed 195-50-15 (4.1.D.1b)**Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Stop lamp not working (1.2.1b)**MOT #5** 2016-08-26 08:25**MOT test number** 569293242574**Result** ✓ Passed**MOT #4** 2015-09-01 08:27**MOT test number** 671331790733**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-09-01 00:00**MOT test number** 347352690768**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-08-20 10:41**MOT test number** 348252834250**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2013-08-02 13:18
MOT test number	946964413233
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
5 September 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	5 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-07-30
Last registration	2023-09-05
Complete history	See info



Registration #1	2010-07-30	21 mi
Registration #2	2013-08-02	43.519 mi
Registration #3	2014-08-20	50.698 mi
Registration #4	2015-09-01	55.843 mi
Registration #5	2015-09-01	55.843 mi
Registration #6	2016-08-26	59.206 mi
Registration #7	2017-08-30	62.726 mi
Registration #8	2017-08-30	62.733 mi
Registration #9	2018-09-04	67.718 mi
Registration #10	2018-09-06	67.725 mi
Registration #11	2019-09-05	72.717 mi
Registration #12	2019-09-05	72.717 mi
Registration #13	2019-09-05	72.717 mi
Registration #14	2019-09-05	72.717 mi
Registration #15	2019-09-05	72.717 mi
Registration #16	2019-09-05	72.717 mi
Registration #17	2019-09-05	72.717 mi
Registration #18	2019-09-05	72.717 mi
Registration #19	2019-09-05	72.717 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	AL64550