





report date: 2024-03-29

General information

Make	FIAT
Model	PANDA POP
Colour	Silver
Year of manufacture	2016
Top speed	102 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date	2022-11-14
Pictures	0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 1

Date	2021-02-04	
Pictures	11	
Listing price	<u>View report</u>	









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-08-15
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	16
Total items failed	5

MOT #8	2023-08-16 16:25
MOT test number	919658778028
Result	✓ Passed
Next expiry date	2024-08-15
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 175/65/15 (5.2.3 (e))	

MOT #7		2022-08-12 14:19
MOT test	number	113048886061
Result		✓ Passed
Advice	Offside Front rear veiw mirror damaged	
Advice (5.3.4 (a)	Nearside Front Lower Suspension arm pin or bush worn but not resulting i (i))	in excessive movement

MOT #6	2022-08-12 12:38
MOT test number	330225294059
Result	× Failed
Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in e (5.3.4 (a) (i))	xcessive movement
Advice Offside Front rear veiw mirror damaged	
Fail Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i)))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2021-11-04 14:28 **MOT** test number 624581677394 Result × Failed Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt **Minor** Offside Rear Tyre obviously under inflated (5.2.3 (I)) Fail Windscreen washer provides insufficient washer liquid (3.5 (a)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3	2020-09-10 09:3	
MOT test number	316274949094	
Result	✓ Passed	

MOT #2 2020-09-02 08:53
MOT test number 983377409288

Result × Failed

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both front brake discs badly corroded and pitted. (1.1.14 (a) (ii))

Advice Rear Shock absorbers has a slightly worn bush Both rear top bushes starting to split. (5.3.2 (c))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1		2019-09-05 15:45
MOT test	number	287162321460
Result		✓ Passed
Advice	Items removed from driver's view prior to test	
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	15 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Tyne	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
THE STATE OF THE S	

THE STATE OF THE S	
HEREER PARTY AND ADDRESS OF THE PARTY AND ADDR	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of sisters	
Current registration	NK SIX
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-09-02
Last registration	2023-08-16
Complete history	See info



Registration #1	2016-09-02	17 mi
Registration #2	2019-09-05	14.115 mi
Registration #3	2020-09-02	17.389 mi
Registration #4	2020-09-10	17.413 mi
Registration #5		11.777 es
Registration #6	2021-11-04	21.855 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		70.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1882 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg

Additional information

Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats	4	
Engine number Carcheck.co.uk	1523903 pag	e 12/12