



HXI4NHJ


report date: 2024-03-28

General information

Make	MINI
Model	JOHN COOPER WORKS COOPER S
Colour	Black
Year of manufacture	2014
Top speed	137 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	55.4 mpg
Consumption combined	42.8 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-11-20
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	17
Total items failed	10

MOT #13	2023-11-20 09:21
MOT test number	531644972977
Result	✓ Passed
Next expiry date	2024-11-20

MOT #12	2022-11-21 12:50
MOT test number	872161237449
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front wheel rim distorted

**MOT #11**

2022-11-18 12:55

MOT test number

820542545418

Result**✗ Failed****Advice** Nearside Front wheel rim distorted**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure cords exposed inner tread (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10**

2022-01-22 10:04

MOT test number

587925614870

Result**✓ Passed****Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9**

2021-02-01 14:44

MOT test number

435282333643

Result**✓ Passed****MOT #8**

2021-01-28 13:05

MOT test number

352268187071

Result**✗ Failed****Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))**Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

**MOT #7** 2020-07-21 11:47**MOT test number** 621878687072**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2020-07-21 11:18**MOT test number** 314868383196**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2019-07-22 14:30**MOT test number** 429312693173**Result** ✓ Passed**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #4** 2019-07-22 11:37**MOT test number** 363622737153**Result** ✗ Failed**Fail** Nearside Front Outer Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Fail** Nearside Front Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #3** 2018-08-01 09:57**MOT test number** 658379373788**Result** ✓ Passed



MOT #2	2018-07-31 14:16
MOT test number	620443282542
Result	✗ Failed
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #1	2017-07-13 15:54
MOT test number	529059652586
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
20 November 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	20 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	HX14NHJ
Plate since	2019-09-29
Current registration	HX14NHJ
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-07-31
Last registration	2023-11-20
Complete history	See info



Registration #1	2014-07-31	23 mi
Registration #2	2017-07-13	52.547 mi
Registration #3	2018-07-31	58.175 mi
Registration #4	2018-08-01	58.175 mi
Registration #5	2019-07-22	61.755 mi
Registration #6	2019-07-22	61.755 mi
Registration #7	2020-07-21	65.428 mi
Registration #8	2020-07-21	65.428 mi
Registration #9	2020-07-21	65.428 mi
Registration #10	2020-07-21	65.428 mi
Registration #11	2020-07-21	65.428 mi
Registration #12	2020-07-21	65.428 mi
Registration #13	2020-07-21	65.428 mi
Registration #14	2020-07-21	65.428 mi
Registration #15	2020-07-21	65.428 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1255 kg
Max. allowed weight	1685 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
-----------------	---

Number of axles	2
Engine number	A174J821