





report date: 2024-03-29

General information

| Make | FORD |
|---------------------|---------------------|
| Model | S-MAX TITANIUM TDCI |
| Colour | Blue |
| Year of manufacture | 2014 |
| Top speed | 120 mph |
| 0 - 100 km/h | 10.9 seconds |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 103 kW / 140 HP / 138 BHP |
|-------------------------|---------------------------|
| Max. torque | 320 Nm at 1.750 rpm |
| Engine capacity | 1.997 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 38.2 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 149 g/km |
| CO2 label | F |



CarCheck.co.uk page 1/13



HY14VVN

report date: 2024-03-29

Internet history

Entry 1


Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

| MOT expiry date | 2025-04-22 |
|--------------------|------------|
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 25 |
| Total items failed | 5 |

| MOT #11 | | 2024-03-28 16:29 |
|-----------|--|------------------|
| MOT test | number | 879590271079 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-04-22 |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #10 | 2023-04-10 | 07:50 |
|-----------------|---|-------|
| MOT test i | number 1366297 | 99053 |
| Result | √ F | assed |
| Advice | Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 | 1 (a) |
| Advice (a) (i)) | Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3 | 3.4 |

| MOT #9 | 2022-03-23 08:51 |
|---|------------------|
| MOT test number | 207530627622 |
| Result | ✓ Passed |
| Advice Nearside Rear Exhaust mounting defective (6.1.2 (a)) | |

CarCheck.co.uk page 3/13



Result

HY14VVN report date: 2024-03-29

✓ Passed

MOT #8 2021-04-23 13:19

MOT test number 870209268088

MOT #7 2020-07-25 11:48

MOT test number 700151142719

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

real side freal stilla seat freed flot allowing fall hispection of addit ber

Advice Nearside Front Nail in tyre

Advice Offside Rear Seat belt flexible stalk damaged (7.1.2 (b) (i))

Advice Offside Front wing & door damaged

MOT #6 2019-04-17 10:46

MOT test number 163660898838

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

Advice Brake pedal wearing smooth (1.1.2 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



MOT #5 2018-05-01 09:08

MOT test number 752708663084

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Central Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2017-05-26 14:29

MOT test number 827562132187

Result ✓ Passed

Advice Minor wear brake pedal anti-slip

MOT #3 2017-05-26 07:35

MOT test number 471999512210

Result × Failed

Advice Minor wear brake pedal anti-slip

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Advice Tailgate hard to open

MOT #2 2017-03-06 11:08

MOT test number 313366174516

Result
✓ Passed

Advice Offside Rear tyre worn on inner edge

CarCheck.co.uk page 5/13



HY14VVN

report date: 2024-03-29

MOT #1 2017-03-03 10:31

MOT test number 347557508415

Result X Failed

Advice Offside Rear tyre worn on inner edge

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

CarCheck.co.uk page 6/13



Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 336 |
| MOT expiry date | 22 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

| Owner mistory | |
|--|-------------|
| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is | |
| | |
| ********* | |
| | |
| *************************************** | |
| HEREER STATE OF THE STATE OF TH | |
| *************************************** | |
| THE STREET STREET | |
| Plate changes | More info > |
| See in this check if this FORD had different number plates. | |
| Number of plates | |
| | |
| Current registration | NK SIS |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 10/13



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 11/13



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2014-04-15 |
| Last registration | 2024-03-28 |
| Complete history | See info |



| Registration #1 | 2014-04-15 | 10 mi |
|------------------|------------|-----------|
| Registration #2 | 2017-03-03 | 34.424 mi |
| Registration #3 | 2017-03-06 | 34.424 mi |
| Registration #4 | 2017-05-26 | 35.899 mi |
| Registration #5 | 2017-05-26 | 35.899 mi |
| Registration #6 | 2018-05-01 | 43.118 mi |
| Registration #7 | 2019-04-17 | 50.301 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 es |
| Registration #13 | | 10.777 es |

More info >

CarCheck.co.uk page 12/13



Car features

The FORD factory car options list is only available in the premium report.

S0225 Air conditioning

S0295

S0482

S0501

S0566

S0567

S0569

View the complete FORD factory list for this vehicle <u>here</u>.

More info >

Safety ratings

| NCAP | rating | | | | † | * | † | | | 7 |
|------|--------|--|--|--|----------|---|----------|--|--|---|
|------|--------|--|--|--|----------|---|----------|--|--|---|

Video <u>see crash video</u>



Dimensions & weight

| Width | 2154 mm |
|---------------------|---------|
| Height | 1658 mm |
| Length | 4768 mm |
| Wheel base | 2850 mm |
| Kerb weight | 1688 kg |
| Max. allowed weight | 2505 kg |

Additional information

| Fuel tank capacity | 70 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 13/1: |

Number of axles2Engine numberET47075