



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2300 L2H1 CDTI S/S
Colour	White
Year of manufacture	2014
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.5 mpg
Consumption extra urban	61.3 mpg
Consumption combined	54.2 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 2

Date	2022-06-18
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-09-26
Pictures	18
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-26
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	18
Total items failed	10

MOT #11	2024-03-27 10:01
MOT test number	428121459701
Result	✓ Passed
Next expiry date	2025-03-26
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Shock absorbers has light misting of oil BOTH TOP MOUNTS NOISY (5.3.2 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2024-03-27 10:01
MOT test number	240052929209
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Shock absorbers has light misting of oil BOTH TOP MOUNTS NOISY (5.3.2 (b))

**MOT #9** 2022-12-06 11:58**MOT test number** 290618040806**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** EXHAUST DAMAGED**MOT #8** 2021-11-04 10:20**MOT test number** 110389158888**Result** ✓ Passed**Advice** Dash warning lamps still illuminated when the vehicle is switched to off.**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Exhaust system corroded.**MOT #7** 2021-11-03 14:54**MOT test number** 433093629690**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Coolant level low.**Fail** Offside Front Electrical wiring for braking components extremely deteriorated brake wire broken.
(4.11 (b) (iii))**Advice** Dash warning lamps still illuminated when the vehicle is switched to off.**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Exhaust system corroded.**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**MOT #6** 2021-01-07 15:16**MOT test number** 761774278643**Result** ✓ Passed**MOT #5** 2021-01-07 10:16**MOT test number** 177528731269**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Upper Steering system excessively rough strut top bearing (2.1.1 (a))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #4** 2019-11-06 15:49**MOT test number** 959284741089**Result** ✓ Passed**MOT #3** 2018-11-07 10:57**MOT test number** 862413620196**Result** ✓ Passed**MOT #2** 2018-11-07 10:41**MOT test number** 911470310253**Result** ✗ Failed**Fail** Front Windscreen washer not working (3.5 (a))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #1** 2017-11-07 11:26**MOT test number** 399987129573**Result** ✓ Passed**Advice** Nearside Rear tyre nailed on inner sidewall



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
26 March 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	26 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 FE64KMV
Plate since	2019-09-29
Current registration	 FE64KMV
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-12-31
Last registration	2024-03-27
Complete history	See info



Registration #1	2014-12-31	15 mi
Registration #2	2017-11-07	49.512 mi
Registration #3	2018-11-07	70.987 mi
Registration #4	2018-11-07	70.987 mi
Registration #5	2019-11-06	78.281 mi
Registration #6	2021-01-07	92.637 mi
Registration #7	2021-01-07	92.638 mi
Registration #8	2022-03-27	92.638 mi
Registration #9	2022-03-27	92.638 mi
Registration #10	2022-03-27	92.638 mi
Registration #11	2022-03-27	92.638 mi
Registration #12	2022-03-27	92.638 mi
Registration #13	2022-03-27	92.638 mi
Registration #14	2022-03-27	92.638 mi

More info >



Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	198A30007170306 LJ5