



report date: 2024-03-28

General information

Make	MINI
Model	COUNTRYMAN COOPER SD COOPER SD
Colour	Green
Year of manufacture	2012
Top speed	123 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	61.4 mpg
CO2 emission	122 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-28
Pictures	24
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-12
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	27
Total items failed	3

MOT #14	2023-07-11 08:43
MOT test number	490401573748
Result	✓ Passed
Next expiry date	2024-07-12
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))

MOT #13	2022-07-13 07:54
MOT test number	516849451559
Result	✓ Passed

**MOT #12**

2022-07-11 12:36

**MOT test number**

594483304259

**Result****✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Macpherson strut mounting damaged but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Macpherson strut mounting damaged but not seriously weakened (5.3.3 (b) (i))
- DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2021-06-29 07:24

**MOT test number**

620662376154

**Result****✓ Passed****MOT #10**

2020-07-21 10:12

**MOT test number**

367077743387

**Result****✓ Passed**

- Advice** Chip in windscreen
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Both rear tyres are castellated
- Advice** Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))

**MOT #9**

2019-08-06 14:34

**MOT test number**

747258951448

**Result****✓ Passed**

**MOT #8** 2019-08-05 11:55**MOT test number** 312750530590**Result** ✗ Failed**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #7** 2018-07-25 13:20**MOT test number** 566026268898**Result** ✓ Passed**MOT #6** 2018-07-20 08:30**MOT test number** 272993516273**Result** ✗ Failed**Advice** Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e))**MAJOR** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**MAJOR** Anti-roll bar pin or bush excessively worn Both rear (5.3.4 (a) (i))**MAJOR** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**MOT #5** 2017-07-06 10:14**MOT test number** 115829747998**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #4** 2017-07-06 10:14**MOT test number** 933645547934**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2016-08-06 08:25**MOT test number** 149571877650**Result** ✓ Passed**Advice** Tyre worn close to the legal limit Both front (4.1.E.1)**MOT #2** 2015-06-19 13:12**MOT test number** 748570075108**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2015-06-18 17:03**MOT test number** 885439865149**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
12 July 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	12 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-06-30
Last registration	2023-07-11
Complete history	<a href="#">See info</a>



Registration #1	2012-06-30	18 mi
Registration #2	2015-06-18	61.923 mi
Registration #3	2015-06-19	61.923 mi
Registration #4	2016-08-06	81.254 mi
Registration #5	2017-07-06	87.257 mi
Registration #6	2017-07-06	87.257 mi
Registration #7	2018-07-20	101.127 mi
Registration #8	2018-07-25	101.152 mi
Registration #9	2019-06-20	101.152 mi
Registration #10	2019-06-20	101.152 mi
Registration #11	2019-06-20	101.152 mi
Registration #12	2019-06-20	101.152 mi
Registration #13	2019-06-20	101.152 mi
Registration #14	2019-06-20	101.152 mi
Registration #15	2019-06-20	101.152 mi
Registration #16	2019-06-20	101.152 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1320 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	72588135
---------------	----------