



TOYOTA

WCZI230

report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO VVTI T3
Colour	Red
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg





Internet history

Entry 1

Date	2021-07-17
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT #8	2022-04-05 15:53
MOT test number	470618906089
Result	✓ Passed
Next expiry date	2023-04-04
Minor	Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Headlamp lens slightly defective Both (4.1.1 (b) (i))

MOT #7	2022-03-29 11:56
MOT test number	990467547632
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Minor	Nearside Front Lower Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Chassis (5.3.6 (a) (i))
Minor	Headlamp lens slightly defective Both (4.1.1 (b) (i))
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Fail	Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Outer Under Sill and Inner wheel arch (5.3.6 (a) (i))

MOT #6	2021-02-02 13:32
MOT test number	788181184675
Result	✓ Passed
Advice	Brake pad(s) wearing thin all (1.1.13 (a) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #5** 2021-01-26 14:03**MOT test number** 570790479240**Result** ✗ Failed

- Advice** Brake pad(s) wearing thin all (1.1.13 (a) (ii))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Rear Brake pad(s) incorrectly mounted (1.1.13 (c))
- Fail** Nearside Rear Brake pad(s) incorrectly mounted (1.1.13 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #4 2020-01-23 16:11**MOT test number** 418235559411**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Anti-roll bar linkage ball joint has slight play both front (5.3.4 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material both rear (1.1.11 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Sub-frame pin or bush worn but not resulting in excessive movement both rear (5.3.4 (a) (i))

**MOT #3**

2020-01-18 12:05

MOT test number

113235620168

Result

✗ Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brake pipe corroded, covered in grease or other material both rear (1.1.11 (c))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Anti-roll bar linkage ball joint has slight play both front (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Sub-frame pin or bush worn but not resulting in excessive movement both rear (5.3.4 (a) (i))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #2**

2019-01-22 13:56

MOT test number

288702519956

Result

✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #1**

2018-01-16 12:49

MOT test number

539812222660

Result

✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 10,000
Average private trade value	£ 12,500

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2004-02-20
Last registration	2022-04-05
Complete history	See info



Registration #1	2004-02-20	10 mi
Registration #2	2018-01-16	137.347 mi
Registration #3	2019-01-22	149.890 mi
Registration #4	2020-01-18	163.842 mi
Registration #5	2020-01-23	163.903 mi
Registration #6	2020-01-23	163.903 mi
Registration #7	2020-01-23	163.903 mi
Registration #8	2020-01-23	163.903 mi
Registration #9	2020-01-23	163.903 mi
Registration #10	2020-01-23	163.903 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2600 mm
Kerb weight	1295 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	1ZZ1667390