





General information

Make	CITROEN
Model	C5 SX
Colour	Silver
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	10.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 3.750 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.5 mpg
Consumption extra urban	44.8 mpg
Consumption combined	34.9 mpg
CO2 emission	192 g/km
CO2 label	J







Internet history

Entry 5	
Date	2021-08-10
Pictures	13
Listing price	View report



source: autotrader.co.uk

.

Entry 4	
Date	2021-07-27
Pictures	13
Listing price	View report



source: autotrader.co.uk

Entry 3	
Date	2021-07-10
Pictures	13
Listing price	View report



source: autotrader.co.uk

Pictures

Listing price

13

View report



source: autotrader.co.uk

Entry 1	
Date	2021-06-10
Pictures	13
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-05
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	16
Total items failed	7

MOT #16	2023-09-05 14:40
MOT test number	642255905523
Result	✓ Passed
Next expiry date	2024-09-05
Advice Intermitent misfire multiple cylinders	
Advice Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	

MOT #15	2022-09-06 12:47
MOT test number	710889411489
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge tyres on both sides from	nt (5.2.3 (e))

МОТ #14	2022-09-06 08:27
MOT test number	309641990384
Result	🗙 Failed
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Fail Nearside Headlamp aim not tested (4.1.2 (b))	



GD59NVB
report date: 2024-03-28

MOT #13	2021-06-25 13:58
MOT test number	103530146870
Result	✓ Passed
MOT #12	2020-10-07 13:01
MOT test number	252236170675
Result	✓ Passed

Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened face (1.1.14 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2019-10-10 10:49
MOT test number	187667581070
Result	✓ Passed
Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #10	2018-10-09 08:13
MOT test number	697935083839
Result	✓ Passed
Advice Offside Daytime Running Lamp not working	

MOT #9		2018-10-09 08:13
MOT test number		848880355661
Result		🗙 Failed
Advice Offside Daytime Running Lamp not working		
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a))	





2017-09-26 13:56

668128974548
✓ Passed

MOT #7

MOT test number		590592986689
Result		🗙 Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	
Advice Offside Front da	y light running lamp inop	
Advice EML ON		

MOT #6		2016-10-11 08:19
MOT test	number	698628071850
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Engine management light on	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2015-11-05 11:25
MOT test number	124273197437
Result	✓ Passed
MOT #4	2014-11-17 10:07

MOT test number	866601924323
Result	✓ Passed





MOT #3	2013-11-05 13:55
MOT test number	168399803339
Result	✓ Passed
MOT #2	2013-11-05 12:03
MOT test number	529689503304
Result	🗙 Failed
Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)	
MOT #1	2012-10-05 10:55
MOT test number	497199272222

Result

🗸 Passed



Tax & MOT check

✓ Taxed	✓ MOT
1 December 2024 Tax status	Expires: 5 September 2024 Valid until 1 December
Days left	215
MOT expiry date	5 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lamp
Туре		
Damage 2		AMPL
Date		· · ·
Category	1000000	AMPL
Туре		

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plata since	





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



GD59NVB report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-09-17
Last registration	2023-09-05
Complete history	See info



Registration #1	2009-09-17	8 mi
Registration #2	2012-10-05	29.477 mi
Registration #3	2013-11-05	36.827 mi
Registration #4	2013-11-05	36.829 mi
Registration #5	2014-11-17	46.342 mi
Registration #6	2015-11-05	56.380 mi
Registration #7	2016-10-11	64.728 mi
Registration #8	2017-09-26	71.798 mi
Registration #9	2017-09-26	71.798 mi
Registration #10	2018-10-09	80.446 mi
Registration #11	2018-10-09	80.446 mi
Registration #12		11.777 est
Registration #12 Registration #13		11.227 est 21.227 est
-		01.000 est 01.000 est 01.000 est
Registration #13		0.000 est 0.000 est 0.000 est 0.000 est
Registration #13 Registration #14		0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #13 Registration #14 Registration #15		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es
Registration #13 Registration #14 Registration #15 Registration #16		0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		01,222 46 01,222 46 01,222 46 01,222 46 01,222 46 01,222 46 01,222 46 01,222 46
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46 0.227 46



GD59NVB report date: 2024-03-28

Safety ratings		
NCAP rating	****	
Video	see crash video	
Dimensions & weight		
Width		1853 mm
Height		1471 mm
Length		4829 mm
Wheel base		2815 mm
Kerb weight		1549 kg
Max. allowed weight		2154 kg
Additional information		
Fuel tank capacity		66 I
Fuel delivery		Multi-Point Injection
Number of doors		5
Number of seats		5
Number of axles		2
Engine number		LT351739872