





report date: 2024-03-28

### General information

Make	SUZUKI
Model	CELERIO SZ4
Colour	White
Year of manufacture	2017
Top speed	97 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.500 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/11



report date: 2024-03-28

### Internet history

### Entry 1

Date	2021-02-04
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/11



ST67MYS
report date: 2024-03-28

MOT history

MOT expiry date	2025-04-06
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #5	2024-04-03 11:22
MOT test number	184384164162
Result	✓ Passed
Next expiry date	2025-04-06
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #4	2023-04-04	1 09:10
MOT test	number 5276320	066232
Result	<b>✓</b>	Passed
Advice (c))	Offside Brake pipe corroded, covered in grease or other material front to rear brake pipe. (1.	1.11
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing 165/65/14 (5.2.3 (d) (ii))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear facing bush in arm. (5.3.4 (a) (i))		ar
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3 2023-04-04 08:43

**MOT test number** 149153426858

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing 165/65/14 (5.2.3 (d) (ii))

Fail Brake lever has insufficient reserve travel Parking brake lever. (1.1.2 (a))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear facing bush in arm. (5.3.4 (a) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Brake pipe corroded, covered in grease or other material front to rear brake pipe. (1.1.11

(c))

MOT #2 2022-04-06 10:52

**MOT test number** 537586200185

**Result** ✓ Passed

MOT #1 2021-04-07 14:36

**MOT test number** 539592769492

**Result** ✓ Passed

CarCheck.co.uk page 4/11



ST67MYS
report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	6 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	Е
First licence fee (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history
---------------

For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
*******	
***************************************	
	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	
Current registration	UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

### Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-11-24
Last registration	2024-04-03
Complete history	See info



Registration #1	2017-11-24	18 mi
Registration #2		71.777 es
Registration #3	2021-04-07	12.365 mi
Registration #4	2022-04-06	17.616 mi
Registration #5		11.117 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

### Safety ratings

NCAP rating	***
Adult	61%
Children	74%
Pedestrian	68%
Safety systems	38%
Overall rating	60%
Video	see crash video



## Dimensions & weight

Width	1600 mm
Height	1540 mm
Length	3600 mm
Wheel base	2425 mm
Kerb weight	880 kg
Max. allowed weight	1260 kg

### Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K10BS1060891

CarCheck.co.uk page 11/11