



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | C30 D3 ES |
| Colour | Silver |
| Year of manufacture | 2011 |
| Top speed | 130 mph |
| 0 - 60 mph | 8.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 350 Nm at 1.500 rpm |
| Engine capacity | 1.984 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 40.4 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 134 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-02-09 |
| Pictures | 12 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2024-05-11 |
| MOT pass rate | 79 % |
| MOT passed | 11 |
| Failed MOT tests | 3 |
| Total advice items | 16 |
| Total items failed | 7 |

| | |
|-------------------------|------------------|
| MOT #14 | 2023-05-12 06:53 |
| MOT test number | 175610382494 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-11 |

| | |
|------------------------|---|
| MOT #13 | 2023-05-11 09:24 |
| MOT test number | 824009853922 |
| Result | ✗ Failed |
| Fail | Nearside Front Position lamp not working (4.2.1 (a) (ii)) |
| Fail | Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |
| Fail | Offside Front Position lamp not working (4.2.1 (a) (ii)) |
| Fail | Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |

| | |
|------------------------|------------------|
| MOT #12 | 2022-11-15 16:02 |
| MOT test number | 860117847660 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #11 | 2021-12-06 15:51 |
| MOT test number | 219714995823 |
| Result | ✓ Passed |

**MOT #10**

2021-12-02 08:14

MOT test number

604471107758

Result

✗ Failed

Fail Nearside Rear Brake disc in such a condition that it is seriously weakened inner face (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (Both) Worn/corroded (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9**

2020-12-07 14:00

MOT test number

305957765285

Result

✓ Passed

Advice Rear Tyre worn close to legal limit/worn on edge inside edges (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8**

2019-12-05 14:46

MOT test number

610906388056

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7**

2019-12-04 10:45

MOT test number

843400217405

Result

✗ Failed

Fail Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



| | |
|------------------------|--|
| MOT #6 | 2018-11-17 09:56 |
| MOT test number | 520428894185 |
| Result | ✓ Passed |
| Advice | Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i)) |

| | |
|------------------------|--|
| MOT #5 | 2017-12-01 10:55 |
| MOT test number | 459701636113 |
| Result | ✓ Passed |
| Advice | Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Rearmost bush (2.4.G.2) |
| Advice | Nearside Rear Outer Suspension arm rubber bush deteriorated but not resulting in excessive movement Link arm (2.4.G.2) |
| Advice | Rear Brake pad(s) wearing thin (3.5.1g) |
| Advice | Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement Rearmost bush (2.4.G.2) |
| Advice | Offside Rear Outer Suspension arm rubber bush deteriorated but not resulting in excessive movement Link arm (2.4.G.2) |

| | |
|------------------------|------------------|
| MOT #4 | 2016-12-05 09:29 |
| MOT test number | 423492456065 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #3 | 2015-12-08 12:15 |
| MOT test number | 662194148124 |
| Result | ✓ Passed |

| | |
|------------------------|--|
| MOT #2 | 2015-01-05 11:06 |
| MOT test number | 395515605003 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |



| | |
|-----------------|---|
| MOT #1 | 2014-01-06 16:26 |
| MOT test number | 869926204048 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
11 May 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 93 |
| MOT expiry date | 11 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2011-01-31 |
| Last registration | 2023-05-12 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-01-31 | 8 mi |
| Registration #2 | 2014-01-06 | 17.015 mi |
| Registration #3 | 2015-01-05 | 22.396 mi |
| Registration #4 | 2015-12-08 | 26.730 mi |
| Registration #5 | 2016-12-05 | 45.153 mi |
| Registration #6 | 2017-12-01 | 60.599 mi |
| Registration #7 | 2018-11-17 | 75.202 mi |
| Registration #8 | 2019-12-04 | 87.506 mi |
| Registration #9 | 2020-05-20 | 95.377 mi |
| Registration #10 | 2020-05-20 | 95.377 mi |
| Registration #11 | 2020-05-20 | 95.377 mi |
| Registration #12 | 2020-05-20 | 95.377 mi |
| Registration #13 | 2020-05-20 | 95.377 mi |
| Registration #14 | 2020-05-20 | 95.377 mi |
| Registration #15 | 2020-05-20 | 95.377 mi |
| Registration #16 | 2020-05-20 | 95.377 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1454 mm |
| Length | 4476 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1504 kg |
| Max. allowed weight | 2020 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 1012435 |