



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF S
Colour	Black
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #17</b>	2022-09-09 12:34
<b>MOT test number</b>	355913460262
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-09-15

<b>MOT #16</b>	2021-09-16 12:12
<b>MOT test number</b>	936705890766
<b>Result</b>	✓ Passed

<b>MOT #15</b>	2021-09-14 15:29
<b>MOT test number</b>	981492090925
<b>Result</b>	✗ Failed
<div><div>Fail</div>Offside Rear Road wheel fixing missing (5.2.1 (a) (i))</div>	
<div><div>Fail</div>Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))</div>	
<div><div>Fail</div>Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))</div>	
<div><div>Fail</div>Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))</div>	
<div><div>Fail</div>Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))</div>	
<div><div>Fail</div>Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))</div>	

<b>MOT #14</b>	2020-04-03 17:16
<b>MOT test number</b>	328221664868
<b>Result</b>	✓ Passed

<b>MOT #13</b>	2018-11-13 11:13
<b>MOT test number</b>	271111281738
<b>Result</b>	✓ Passed
<div><div>Minor</div>Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))</div>	
<div><div>Advice</div>Nearside Rear Brake lining(s) wearing thin (1.1.13 (a) (ii))</div>	

**MOT #12** 2017-10-07 09:09**MOT test number** 737876656610**Result** ✓ Passed**MOT #11** 2017-10-07 09:09**MOT test number** 166992603442**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #10** 2016-09-26 11:33**MOT test number** 824005028300**Result** ✓ Passed**MOT #9** 2016-09-26 11:33**MOT test number** 419986203253**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #8** 2015-09-14 11:36**MOT test number** 794087630666**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-09-14 11:17**MOT test number** 920630051945**Result** ✗ Failed**Fail** Offside Rear Inner Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2015-09-14 00:00**MOT test number** 140362068291**Result** ✓ Passed**MOT #5** 2015-09-14 00:00**MOT test number** 973093246498**Result** ✗ Failed

**Pass with rectification** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #4** 2014-09-08 13:58**MOT test number** 169441054266**Result** ✓ Passed

**Notice** Vehicle's internal headlight adjuster altered to recheck lights

**Advice** Offside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #3** 2014-09-08 13:58**MOT test number** 388701854202**Result** ✗ Failed

**Advice** Offside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**Pass with rectification** Nearside Headlamp aim too low (1.8)

**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)

**Notice** Vehicle's internal headlight adjuster altered to recheck lights

**Pass with rectification** Offside Headlamp aim too low (1.8)

**MOT #2** 2013-09-06 12:11**MOT test number** 935079743250**Result** ✓ Passed



MOT #1	2012-09-26 16:47
MOT test number	595340072207
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>YD590MC</b>
Plate since	2024-03-28
Current registration	 <b>YD590MC</b>
Plate since	2024-03-28

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-30
Last registration	2022-09-09
Complete history	<a href="#">See info</a>



Registration #1	2009-09-30	27 mi
Registration #2	2012-09-26	23.818 mi
Registration #3	2013-09-06	31.233 mi
Registration #4	2014-09-08	40.237 mi
Registration #5	2015-09-14	48.466 mi
Registration #6	2015-09-14	48.466 mi
Registration #7	2015-09-14	48.466 mi
Registration #8	2015-09-14	48.466 mi
Registration #9	2016-09-26	57.634 mi
Registration #10	2016-09-26	57.634 mi
Registration #11	2016-09-26	57.634 mi
Registration #12	2016-09-26	57.634 mi
Registration #13	2016-09-26	57.634 mi
Registration #14	2016-09-26	57.634 mi
Registration #15	2016-09-26	57.634 mi
Registration #16	2016-09-26	57.634 mi
Registration #17	2016-09-26	57.634 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1142 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAX 206347