



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2300 L2H1 CDTI S/S ECOFLEX
Colour	White
Year of manufacture	2015
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-10-02
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-15
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	31
Total items failed	4

MOT #12	2023-11-16 17:09
MOT test number	149760145786
Result	✓ Passed
Next expiry date	2024-11-15
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11	2023-11-16 16:13
MOT test number	379854956334
Result	✗ Failed
MAJOR	Nearside Side repeater not working (4.4.1 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #10**

2022-11-16 17:08

MOT test number

202868848228

Result

✓ Passed

- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #9

2022-11-15 13:27

MOT test number

988918012626

Result

✗ Failed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- MAJOR** Fuel system component leaking engine bay (6.1.3 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Fuel cap/sealing device ineffective (6.1.3 (b) (i))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #8

2021-09-13 17:15

MOT test number

209526412353

Result

✓ Passed

MOT #7

2021-08-23 08:17

MOT test number

664202257819

Result

✗ Failed

- MAJOR** Exhaust emissions exceed default limit of 0.7m-1 (8.2.2.2 (b))

**MOT #6** 2020-09-15 12:04**MOT test number** 690702944825**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2020-09-15 11:00**MOT test number** 355075019113**Result** ✗ Failed**DANGEROUS** Offside Front Macpherson strut likely to fail (5.3.3 (b) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2019-10-12 09:33**MOT test number** 577668656163**Result** ✓ Passed**Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Side repeater slightly discoloured (4.4.3 (a))

**MOT #3** 2018-10-08 14:07**MOT test number** 812901531651**Result** ✓ Passed**Advice** Undertray fitted**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Offside Seat belt slightly damaged (7.1.2 (b) (i))**MOT #2** 2018-01-29 08:25**MOT test number** 920488194784**Result** ✓ Passed**MOT #1** 2018-01-22 15:59**MOT test number** 343166499681**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit 195/60R16C 99/97H (4.1.E.1)**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Brake pedal anti-slip provision missing (3.3.A.1b)**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Both front tyres worn on inner edge



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
15 November 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	15 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-01-28
Last registration	2023-11-16
Complete history	See info



Registration #1	2015-01-28	14 mi
Registration #2	2018-01-22	71.271 mi
Registration #3	2018-01-29	71.272 mi
Registration #4	2018-10-08	75.986 mi
Registration #5	2019-10-12	85.711 mi
Registration #6	2020-09-15	92.470 mi
Registration #7	2020-09-15	92.470 mi
Registration #8	2020-09-15	92.470 mi
Registration #9	2020-09-15	92.470 mi
Registration #10	2020-09-15	92.470 mi
Registration #11	2020-09-15	92.470 mi
Registration #12	2020-09-15	92.470 mi
Registration #13	2020-09-15	92.470 mi
Registration #14	2020-09-15	92.470 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1880 mm
Length	4740 mm
Wheel base	3105 mm
Kerb weight	1330 kg
Max. allowed weight	2330 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	263A20005492603 LN9