




General information

Make	MASERATI
Model	3200GT GT V8
Colour	Grey
Year of manufacture	2001
Top speed	174 mph
0 - 60 mph	5.1 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	363 BHP
Max. torque	490 Nm at 4.500 rpm
Engine capacity	3.217 cc
Cylinders	8
Fuel type	Petrol
Consumption city	10.7 mpg
Consumption extra urban	21.4 mpg
Consumption combined	15.6 mpg
CO2 emission	420 g/km
CO2 label	M






Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2020-10-09
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	9
Total items failed	31

MOT #21	2019-04-09 15:53
MOT test number	858989468362
Result	✓ Passed
Next expiry date	2020-10-09

MOT #20	2018-04-10 13:18
MOT test number	494206389803
Result	✓ Passed

MOT #19	2017-01-31 16:26
MOT test number	442754337373
Result	✓ Passed

MOT #18	2015-07-29 16:35
MOT test number	326180915403
Result	✓ Passed

**MOT #17**

2015-07-24 12:40

MOT test number

686775305236

Result**✗ Failed**

- Fail** Offside Rear fog lamp not working (1.3.2b)
- Fail** Offside Steering rack gaiter split (2.2.D.2d)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #16

2015-07-16 17:15

MOT test number

755037195172

Result**✗ Failed**

- Fail** Parking brake lever ratchet mechanism is excessively worn (3.1.5)
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Notice** E/M/L engine light stays on. Front tyres have perishing present. O/S/Rear tyre has cuts to sidewalls also sidewall separation present.
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Steering rack gaiter split (2.2.D.2d)
- Fail** Nearside Front Additional braking device insecure (3.6.I.1)
- Fail** Headlamp not working on dipped beam (1.7.5a)
- Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #15** 2014-07-17 11:37**MOT test number** 207878694135**Result** ✓ Passed**MOT #14** 2012-11-29 11:31**MOT test number** 458374732366**Result** ✓ Passed**MOT #13** 2012-11-22 16:01**MOT test number** 845477822359**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #12** 2011-11-28 11:31**MOT test number** 428552731472**Result** ✓ Passed**MOT #11** 2011-01-12 16:59**MOT test number** 557822311035**Result** ✓ Passed**MOT #10** 2011-01-05 14:57**MOT test number** 706475401011**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Steering rack gaiter split (2.2.D.2d)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #9** 2009-12-14 12:27**MOT test number** 691508249309**Result** ✓ Passed**MOT #8** 2008-12-10 12:40**MOT test number** 263805048323**Result** ✓ Passed**MOT #7** 2008-12-02 11:37**MOT test number** 443587538496**Result** ✗ Failed**Notice** Oil leak**Fail** Offside Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2007-12-13 16:06**MOT test number** 441947447356**Result** ✓ Passed

**MOT #5**

2007-12-05 15:23

MOT test number

492679537385

Result**✗ Failed****Fail** Brake pedal reservoir fluid level decreases after several brake applications (3.3.C.1)**Fail** Nearside Front Braking system leaking (3.6.A.1)**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Offside Rear Exhaust has part of the system excessively deteriorated (7.1.1a)**Fail** Brake pedal spongy (3.3.B.1b)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Advice** Nearside Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Fail** Brake pedal creeps down while the pedal is held under pressure (3.3.B.1a)**MOT #4**

2007-11-19 17:21

MOT test number

680303827326

Result**✗ Failed****Fail** Offside Rear Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Nearside Rear Exhaust has a major leak of exhaust gases (7.1.2)**MOT #3**

2007-05-10 17:14

MOT test number

440130437123

Result**✗ Failed****Fail** Nearside Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2006-07-31 16:35
---------------	------------------

MOT test number	133232916239
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2005-08-01 17:54
---------------	------------------

MOT test number	344293715215
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

×
Untaxed**Tax expired:**
1 June 2013**×**
MOT**Expired:**
9 October 2020**Tax status**

Expired at 1 June 2013

Days left

3955 days too late

MOT expiry date

9 October 2020

Full MOT history[See MOT history](#)

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this MASERATI. See if, where and when this MASERATI had damage and the car repair costs. We also check if this MASERATI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MASERATI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

[More info >](#)



Vehicle valuation

What is this car worth? See the vehicle value of this MASERATI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MASERATI? How many owners did this MASERATI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MASERATI had different number plates.

Number of plates	1
Current registration	 Y698DGN
Plate since	2019-09-29
Current registration	 Y698DGN
Plate since	2019-09-29

More info >



Finance check

Check if this MASERATI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MASERATI has been settled.

If not, and you buy this MASERATI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MASERATI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2001-06-26
Last registration	2019-04-09
Complete history	See info



Registration #1	2001-06-26	27 mi
Registration #2	2005-08-01	24,249 mi
Registration #3	2006-07-31	31,303 mi
Registration #4	2007-05-10	4,377 mi
Registration #5	2007-11-19	35,005 mi
Registration #6	2007-12-05	35,107 mi
Registration #7	2007-12-13	35,114 mi
Registration #8	2008-12-02	38,833 mi
Registration #9	2008-12-10	38,840 mi
Registration #10	2009-12-14	41,966 mi
Registration #11	2011-01-05	43,388 mi
Registration #12	2011-01-12	43,392 mi
Registration #13	2019-04-09	43,392 mi
Registration #14	2019-04-09	43,392 mi
Registration #15	2019-04-09	43,392 mi
Registration #16	2019-04-09	43,392 mi
Registration #17	2019-04-09	43,392 mi
Registration #18	2019-04-09	43,392 mi
Registration #19	2019-04-09	43,392 mi
Registration #20	2019-04-09	43,392 mi
Registration #21	2019-04-09	43,392 mi
Registration #22	2019-04-09	43,392 mi
Registration #23	2019-04-09	43,392 mi

[More info >](#)

**Additional information**

Fuel tank capacity	90 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	003614