



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE S
Colour	White
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2022-01-03
Pictures	10
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2022-11-25
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	27
Total items failed	10

MOT #14	2021-11-15 10:37
MOT test number	383661256875
Result	✓ Passed
Next expiry date	2022-11-25
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2020-11-17 10:44
MOT test number	841991366708
Result	✓ Passed
Advice	Front shocks appear soft ,no obvious leaks at time of test
Advice	Headlamps set on upper max limit ,advise adjusting down asap

MOT #12	2019-11-26 16:27
MOT test number	860179381616
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Covers fitted to underside of vehicle

**MOT #11**

2019-11-20 10:48

MOT test number

649288397118

Result**✗ Failed****Advice**

Covers fitted to underside of vehicle

Fail

Nearside Headlamp aim too low manual adjuster not working (4.1.2 (a))

Fail

Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail

Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail

Nearside Headlamp aim too far to the left manual adjuster missing (4.1.2 (a))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail

Offside Headlamp aim too low manual adjuster not working (4.1.2 (a))

Fail

Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail

Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #10

2018-11-24 11:11

MOT test number

203957719201

Result**✓ Passed****Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #9** 2018-11-23 15:38**MOT test number** 733098939292**Result** ✗ Failed**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2017-11-20 13:08**MOT test number** 601353099332**Result** ✓ Passed**MOT #7** 2016-10-26 15:27**MOT test number** 172725139193**Result** ✓ Passed**MOT #6** 2016-10-26 11:01**MOT test number** 963308743522**Result** ✗ Failed**Fail** Rear registration plate delaminated (6.3.1d)**MOT #5** 2015-10-31 09:51**MOT test number** 216684972184**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #4** 2015-10-30 10:24**MOT test number** 352590502768**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to the legal limit also perished slightly (4.1.E.1)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Front Tyre worn close to the legal limit also worn on inner edge (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit also worn uneven on inner edge and perished inner sidewall (4.1.E.1)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #3 2014-10-31 12:30**MOT test number** 747114604354**Result** ✓ Passed

- Notice** N/s/f tyre starting to wear on inner edge
- Notice** N/s/r tyre starting to wear on inner edge
- Notice** O/s/f tyre worn on inner edge
- Notice** O/s/r tyre worn on inner edge and side wall cracking
- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)

MOT #2 2013-11-01 13:51**MOT test number** 378955503315**Result** ✓ Passed



MOT #1	2012-11-14 11:32
MOT test number	787749512343
Result	✓ Passed
Notice	Emissions too low to trigger the smoke meter
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-11-24
Last registration	2021-11-15
Complete history	See info



Registration #1	2009-11-24	11 mi
Registration #2	2012-11-14	24.222 mi
Registration #3	2013-11-01	29.248 mi
Registration #4	2014-10-31	34.625 mi
Registration #5	2015-10-30	51.069 mi
Registration #6	2015-10-31	51.071 mi
Registration #7	2016-10-26	73.781 mi
Registration #8	2016-10-26	73.781 mi
Registration #9	2016-10-26	73.781 mi
Registration #10	2016-10-26	73.781 mi
Registration #11	2016-10-26	73.781 mi
Registration #12	2016-10-26	73.781 mi
Registration #13	2016-10-26	73.781 mi
Registration #14	2016-10-26	73.781 mi
Registration #15	2016-10-26	73.781 mi
Registration #16	2016-10-26	73.781 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1408 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	884000
---------------	--------