



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC 110
Colour	Blue
Year of manufacture	2009
Top speed	117 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-05-26
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-31
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	20
Total items failed	2

MOT #17	2023-06-01 10:41
MOT test number	982957684639
Result	✓ Passed
Next expiry date	2024-05-31

MOT #16	2023-05-30 11:59
MOT test number	872927251478
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge ON MIN PERMITTED LIMIT NOW (5.2.3 (e))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (iii))
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #15	2022-05-19 14:44
MOT test number	235920044599
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2022-05-19 11:08**MOT test number** 914279526063**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #13** 2021-05-27 08:47**MOT test number** 727453910956**Result** ✓ Passed**MOT #12** 2021-05-27 08:47**MOT test number** 398520832833**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm BOTH FRONT (5.2.3 (e))**MOT #11** 2020-11-06 10:55**MOT test number** 433455106270**Result** ✓ Passed**MOT #10** 2019-11-26 09:25**MOT test number** 331403199591**Result** ✓ Passed

**MOT #9** 2019-11-25 09:16**MOT test number** 325694540938**Result** ✗ Failed**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2018-11-26 13:17**MOT test number** 406608616591**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2018-11-26 09:27**MOT test number** 493421246397**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Front Suspension arm pin or bush excessively worn lower arm rear bush (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn lower arm rear bush (5.3.4 (a) (i))**MOT #6** 2017-11-27 09:14**MOT test number** 560589964482**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** EXHAUST HEAT SHEILD INSECURE**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #5	2016-11-23 08:50
---------------	------------------

MOT test number	919809259484
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2015-11-23 09:01
---------------	------------------

MOT test number	973530256534
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2014-11-24 11:39
---------------	------------------

MOT test number	326278824374
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2013-11-25 11:01
---------------	------------------

MOT test number	427039023493
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
---------------	---

MOT #1	2012-11-26 09:22
---------------	------------------

MOT test number	106581132399
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
31 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	31 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-11-27
Last registration	2023-06-01
Complete history	See info



Registration #1	2009-11-27	24 mi
Registration #2	2012-11-26	34.858 mi
Registration #3	2013-11-25	45.785 mi
Registration #4	2014-11-24	58.571 mi
Registration #5	2015-11-23	68.164 mi
Registration #6	2016-11-23	77.453 mi
Registration #7	2017-11-27	85.669 mi
Registration #8	2018-11-26	93.974 mi
Registration #9	2018-11-26	93.974 mi
Registration #10	2019-11-25	102.673 mi
Registration #11	2019-11-25	102.673 mi
Registration #12	2019-11-25	102.673 mi
Registration #13	2019-11-25	102.673 mi
Registration #14	2019-11-25	102.673 mi
Registration #15	2019-11-25	102.673 mi
Registration #16	2019-11-25	102.673 mi
Registration #17	2019-11-25	102.673 mi
Registration #18	2019-11-25	102.673 mi
Registration #19	2019-11-25	102.673 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9D82683