





report date: 2024-03-28

General information

Make	ТОҮОТА
Model	VERSO VALVEMATIC TR
Colour	Grey
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.1 seconds
Gearbox	7 speed CVT

Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-09-29

Pictures 18

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-07-05
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	19
Total items failed	2

MOT #13	2023-07-06 12:12
MOT test number	696757265366
Result	✓ Passed
Next expiry date	2024-07-05
Advice Offside Front Inner Suspension arm pin or bush worn but not result (5.3.4 (a) (i))	lting in excessive movement
Minor Offside Front Outer Track rod end ball joint dust cover damaged or ingress of dirt (2.1.3 (g) (i))	deteriorated, but preventing the
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Front Inner Suspension arm pin or bush worn but not res (5.3.4 (a) (i))	sulting in excessive movement
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 3/13



MOT #12 2023-07-06 12:12

MOT test number 959455327948

Result X Failed

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Minor Offside Front Outer Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #11 2022-06-07 16:26

MOT test number 522731617574

Result ✓ Passed

MOT #10 2021-09-29 12:10

MOT test number 238029744720

Result \(\sqrt{Passed} \)

MOT #9 2020-10-12 15:47

MOT test number 754891822657

Result ✓ Passed

Advice Both rear springs slightly corroded

MOT #8 2019-10-11 15:23

MOT test number 396323647300

Advice Both rear tyres / cracks on both walls

CarCheck.co.uk page 4/13



MOT #7 2019-10-11 09:33

MOT test number 710945791812

Result X Failed

Advice Both rear tyres / cracks on both walls

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords deep cut (5.2.3 (d) (i))

Advice Offside Front tyre worn bald on inner edge

MAJOR Offside Front Driver's seat fore and aft adjustment mechanism not functioning as intended. not sliding back and forth (6.2.5 (b) (i))

MOT #6 2018-10-12 11:34

MOT test number 980752295126

Result ✓ Passed

MOT #5 2017-10-24 09:10

MOT test number 170545595726

Result \(\sqrt{Passed} \)

Advice Both rear brake discs corroded

MOT #4 2016-10-24 09:11

MOT test number 912202894474

Result

Passed

MOT #3 2015-10-21 09:18

MOT test number 240928042399

Result \(\sqrt{Passed} \)

Advice Nearside Front tyre surface damaged on outer wall

Advice Front brake pads worn low

CarCheck.co.uk page 5/13



MOT #2	2014-10-27 10:03
MOT test number	898730504341
Result	✓ Passed
MOT #1	2013-11-05 09:49
MOT test number	598639703387
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

,	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

Plate changes	More info >
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	IIK SIE
Plate since	
Current registration	NK SIN
Plate since	
	More info

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-11-10
Last registration	2023-07-06
Complete history	See info



Registration #1	2010-11-10	12 mi
Registration #2	2013-11-05	18.895 mi
Registration #3	2014-10-27	25.342 mi
Registration #4	2015-10-21	31.278 mi
Registration #5	2016-10-24	38.178 mi
Registration #6	2017-10-24	45.131 mi
Registration #7	2018-10-12	49.874 mi
Registration #8	2019-10-11	54.680 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		70,777 esc

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles Carcheck.co.uk	2 page 13/13