





report date: 2024-03-28

General information

Make	BMW
Model	116 116D SE
Colour	White
Year of manufacture	2017
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.496 сс
Cylinders	3
Fuel type	Diesel
Consumption city	68.9 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-01-26


Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



LD67KZT

report date: 2024-03-28

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-11-10
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	12
Total items failed	3

MOT #6	2023-11-02 13:52
MOT test number	670430553890
Result	✓ Passed
Next expiry date	2024-11-10

MOT #5		2023-11-02 13:52
MOT test number		463230839657
Result		X Failed
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))	

MOT #4	2022-11-11 10:56
MOT test number	650790811586
Result	✓ Passed
MOT #3	2021-11-01 16:20
MOT test number	465068292907
Result	✓ Passed
Advice Emissions too low to measure	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



LD67KZT

report date: 2024-03-28

2021-10-26 13:27 **MOT** #2 **MOT** test number 293611538569 Result × Failed Pass with rectification Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Emissions too low to measure **Advice DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Pass with rectification Nearside Headlamp aim too low (4.1.2 (a)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Items removed from driver's view prior to test

MOT #1	2020-11-	-03 12:05
MOT test	number 43655	9615569
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a)	(ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e mier metery	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	
manage of the same	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-11-03
Last registration	2023-11-02
Complete history	See info



Registration #1	2017-11-03	15 mi
Registration #2	2020-11-03	47.713 mi
Registration #3	2021-10-26	64.463 mi
Registration #4	2021-11-01	64.464 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin
60295	
60482	
60501	
60566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4329 mm
Wheel base	2690 mm
Kerb weight	1320 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11

Number of axles 2

Engine number 36269896