



T62MLE

report date: 2024-03-28

General information

Make	FIAT
Model	COUPE TURBO 20V LE
Colour	Black
Year of manufacture	1999
Top speed	156 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	217 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	1.998 cc
Cylinders	5
Fuel type	Petrol
Consumption city	19.5 mpg
Consumption extra urban	37.2 mpg
Consumption combined	28.0 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-06-01
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2023-04-07
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	30
Total items failed	15

MOT #21	2022-04-08 11:35
MOT test number	760926624626
Result	✓ Passed
Next expiry date	2023-04-07

MOT #20	2021-03-18 17:07
MOT test number	525639003867
Result	✓ Passed

MOT #19	2021-03-18 10:14
MOT test number	162855843121
Result	✗ Failed
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

MOT #18	2019-06-21 10:48
MOT test number	134653486112
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2018-04-12 11:19
MOT test number	437600050979
Result	✓ Passed

**MOT #16** 2017-05-05 08:13**MOT test number** 955038004037**Result** ✓ Passed**MOT #15** 2016-04-22 13:15**MOT test number** 286660718257**Result** ✓ Passed

- Advice** Damage to offside rear, no sharp edges at this time
- Advice** Front brake discs starting to corrode on inner face, pads 7mm
- Advice** Nearside rear handbrake mechanism / cable starting to stick just passed efficiency
- Advice** Rear brake discs corroding, pads 5mm
- Advice** Light corrosion on jacking points on both sills

**MOT #14** 2015-04-29 10:52**MOT test number** 209699015193**Result** ✓ Passed

- Notice** Advise wheel alignment check for tyre wear
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Offside front tyre wearing bald on inner edge
- Notice** Light corrosion on jacking points
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Rear brake discs corroding

**MOT #13** 2014-04-10 10:48**MOT test number** 437870004128**Result** ✓ Passed**Advice** Offside Outer Front constant velocity joint is slightly worn (2.5.C.1b)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Brake load sensing valve stiff (3.6.E.3)**MOT #12** 2013-03-28 15:02**MOT test number** 137887083049**Result** ✓ Passed**Notice** Rear spring bump stops insecure**MOT #11** 2013-03-20 12:09**MOT test number** 588169973053**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** Rear spring bump stops insecure**MOT #10** 2012-03-27 15:41**MOT test number** 156387482017**Result** ✓ Passed

**MOT #9** 2011-03-29 16:55**MOT test number** 138678181434**Result** ✓ Passed

- Notice** Front inner brake discs slight pitted
- Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Suspension joint offside lower dust cover split/missing
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Rear brake discs pitted
- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)

**MOT #8** 2011-03-29 16:55**MOT test number** 525228481078**Result** ✗ Failed

- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Front inner brake discs slight pitted
- Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Suspension joint offside lower dust cover split/missing
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Rear brake discs pitted

**MOT #7** 2010-04-08 07:37**MOT test number** 891008690027**Result** ✓ Passed



MOT #6	2009-03-30 12:04
MOT test number	291549289018
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5	2008-03-31 12:01
MOT test number	523641698051
Result	✓ Passed

MOT #4	2008-03-31 12:01
MOT test number	551781398043
Result	✗ Failed
Pass with rectification	Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)
Pass with rectification	Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #3	2007-03-30 11:34
MOT test number	472759987079
Result	✓ Passed



MOT #2	2007-03-29 11:59
MOT test number	980208787054
Result	✗ Failed
Fail	Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Nearside Front Brake hose seriously damaged (found during steering lock to lock check) (2.2.D.2b)
Fail	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Offside Rear Rear fog lamp not working (1.3.2b)
Fail	Offside Front Windscreen wiper blade deteriorated (8.2.2)
Fail	Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Offside Front Brake hose seriously damaged (found during steering lock to lock check) (2.2.D.2b)
Fail	Rear fog lamp switch faulty (1.3.1a)
Fail	Nearside Front Windscreen wiper blade deteriorated (8.2.2)

MOT #1	2006-04-03 09:54
MOT test number	884263196067
Result	✓ Passed





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	1999-03-01
Last registration	2022-04-08
Complete history	<a href="#">See info</a>



Registration #1	1999-03-01	29 mi
Registration #2	2006-04-03	44.523 mi
Registration #3	2007-03-29	46.856 mi
Registration #4	2007-03-30	46.856 mi
Registration #5	2008-03-31	1.460 mi
Registration #6	2009-03-30	51.991 mi
Registration #7	2010-04-08	54.008 mi
Registration #8	2011-03-29	55.620 mi
Registration #9	2012-03-27	57.653 mi
Registration #10	2013-03-20	66.126 mi
Registration #11	2013-03-28	66.253 mi
Registration #12	2019-05-29	75.377 mi
Registration #13	2019-05-29	75.377 mi
Registration #14	2019-05-29	75.377 mi
Registration #15	2019-05-29	75.377 mi
Registration #16	2019-05-29	75.377 mi
Registration #17	2019-05-29	75.377 mi
Registration #18	2019-05-29	75.377 mi
Registration #19	2019-05-29	75.377 mi
Registration #20	2019-05-29	75.377 mi
Registration #21	2019-05-29	75.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1768 mm
Height	1340 mm
Length	4250 mm
Wheel base	2540 mm
Kerb weight	1310 kg

Additional information

Fuel tank capacity	63 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	1301694