



report date: 2024-03-28

General information

| | |
|---------------------|----------------------------------|
| Make | VAUXHALL |
| Model | COMBO 2000 L1H1 CDTI S/S ECOFLEX |
| Colour | Red |
| Year of manufacture | 2013 |
| Top speed | 97 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 90 BHP |
| Max. torque | 200 Nm at 1.500 rpm |
| Engine capacity | 1.248 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 47.9 mpg |
| Consumption extra urban | 67.3 mpg |
| Consumption combined | 58.9 mpg |
| CO2 emission | 126 g/km |
| CO2 label | D |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-06 |
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 5 |
| Total items failed | 10 |

| | |
|------------------|------------------|
| MOT #10 | 2023-09-07 13:23 |
| MOT test number | 958912877701 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-06 |

| | |
|-----------------|---|
| MOT #9 | 2023-09-01 12:47 |
| MOT test number | 136460528700 |
| Result | ✗ Failed |
| Fail | Nearside Headlamp lens seriously defective (4.1.1 (b) (ii)) |
| Fail | Nearside Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) |
| Fail | Rear Exhaust system insecure (6.1.2 (a)) |
| Fail | Front Windscreen washer provides insufficient washer liquid (3.5 (a)) |
| Fail | Offside Headlamp lens seriously defective (4.1.1 (b) (ii)) |
| Fail | Offside Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) |

| | |
|-----------------|---|
| MOT #8 | 2022-04-07 14:21 |
| MOT test number | 454301199297 |
| Result | ✓ Passed |
| Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |

**MOT #7** 2022-04-07 14:21**MOT test number** 779239364859**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #6** 2021-03-19 15:49**MOT test number** 178671464237**Result** ✓ Passed**MOT #5** 2020-03-25 15:24**MOT test number** 627431101364**Result** ✓ Passed**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**MOT #4** 2019-04-15 08:44**MOT test number** 309930567103**Result** ✓ Passed**MOT #3** 2018-04-11 09:27**MOT test number** 216533871617**Result** ✓ Passed



| | |
|-----------------|--|
| MOT #2 | 2017-04-11 09:08 |
| MOT test number | 979223038654 |
| Result | ✓ Passed |
| Advice | N/S & O/S Rear O/S Front tyres worn on inner edges |

| | |
|-----------------|------------------|
| MOT #1 | 2016-04-12 08:33 |
| MOT test number | 186309289875 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
6 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 January |
| Days left | 247 |
| MOT expiry date | 6 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|----------------------------------|------------|
| Vehicle class | 39 |
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|----------------------|------------|
| Number of owners | 1 |
| Current owner since | 2019-09-29 |
| Previous owner since | 2019-09-29 |
| Number of owners | 1 |
| Current owner since | 2019-09-29 |
| Previous owner since | 2019-09-29 |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  FG13AYV |
| Plate since | 2019-09-29 |
| Current registration |  FG13AYV |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2013-04-15 |
| Last registration | 2023-09-07 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-04-15 | 22 mi |
| Registration #2 | 2016-04-12 | 38.028 mi |
| Registration #3 | 2017-04-11 | 49.390 mi |
| Registration #4 | 2018-04-11 | 60.172 mi |
| Registration #5 | 2019-04-15 | 69.151 mi |
| Registration #6 | 2020-03-25 | 75.164 mi |
| Registration #7 | 2021-03-25 | 75.164 mi |
| Registration #8 | 2021-03-25 | 75.164 mi |
| Registration #9 | 2021-03-25 | 75.164 mi |
| Registration #10 | 2021-03-25 | 75.164 mi |
| Registration #11 | 2021-03-25 | 75.164 mi |

More info >



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2119 mm |
| Height | 1845 mm |
| Length | 4390 mm |
| Wheel base | 2750 mm |
| Kerb weight | 1270 kg |
| Max. allowed weight | 2020 kg |

Additional information

| | |
|--------------------|---------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of seats | 2 |
| Number of axles | 2 |
| Engine number | 263A20004945108 LN9 |