



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Silver
Year of manufacture	2008
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	96 BHP
Max. torque	126 Nm at 3.200 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	141 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-03
Pictures	2
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-05
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	23
Total items failed	3

## MOT #16 2023-07-14 16:22

MOT test number 969626733779

Result ✓ Passed

Next expiry date 2024-08-05

**Advice** Offside Front Tyre worn close to legal limit/worn on edge and tread cracking (5.2.3 (e))**Advice** Offside and nearside headlight beam patterns poor**Advice** Front Exhaust mounting defective (6.1.2 (a))

## MOT #15 2023-07-13 14:17

MOT test number 860774840495

Result ✗ Failed**Advice** Front Exhaust mounting defective (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge and tread cracking (5.2.3 (e))**Advice** Offside and nearside headlight beam patterns poor**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

## MOT #14 2022-07-14 13:26

MOT test number 455135249202

Result ✓ Passed**Advice** Offside Front tyre wearing on inner edge

**MOT #13** 2021-08-06 10:43**MOT test number** 940055121265**Result** ✓ Passed**MOT #12** 2021-02-24 11:00**MOT test number** 586822198199**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner Edge (5.2.3 (e))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #11** 2020-02-15 09:19**MOT test number** 902818482725**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-02-06 09:56**MOT test number** 280626732006**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inside edge- (5.2.3 (e))**MOT #9** 2018-02-26 13:43**MOT test number** 457718191193**Result** ✓ Passed**Advice** Front Headlamp deteriorated but light output not reduced n/s and o/s (1.7.5a)

**MOT #8** 2018-02-26 13:43**MOT test number** 614470886752**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Front Headlamp deteriorated but light output not reduced n/s and o/s (1.7.5a)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**MOT #7** 2017-02-13 13:45**MOT test number** 611176760959**Result** ✓ Passed**Advice** Offside rear tyre is perished and worn on inside edge**MOT #6** 2016-02-17 10:40**MOT test number** 562510904237**Result** ✓ Passed**Advice** Offside rear tyre is slightly perished**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-02-11 09:21**MOT test number** 337952145098**Result** ✓ Passed**Notice** O/s/f tyre worn on inner edge**MOT #4** 2014-02-06 10:13**MOT test number** 757557534064**Result** ✓ Passed

**MOT #3** 2013-02-18 11:09**MOT test number** 736379243004**Result** ✓ Passed**MOT #2** 2012-02-11 09:54**MOT test number** 138992342056**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-02-25 09:02**MOT test number** 109476551099**Result** ✓ Passed**Notice** NSR TYRE HAS NAIL IN TREAD**Notice** FRONT TYRE WEAR UNEVEN**Notice** OSF TYRE CLOSE TO LIMIT (175/65/14)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
5 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	5 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-02-29
Last registration	2023-07-14
Complete history	<a href="#">See info</a>



Registration #1	2008-02-29	20 mi
Registration #2	2011-02-25	18.379 mi
Registration #3	2012-02-11	24.591 mi
Registration #4	2013-02-18	30.403 mi
Registration #5	2014-02-06	35.596 mi
Registration #6	2015-02-11	39.454 mi
Registration #7	2016-02-17	40.602 mi
Registration #8	2017-02-13	41.655 mi
Registration #9	2018-02-26	44.345 mi
Registration #10	2019-02-20	45.377 mi
Registration #11	2020-02-20	46.377 mi
Registration #12	2021-02-20	47.377 mi
Registration #13	2022-02-20	48.377 mi
Registration #14	2023-02-20	49.377 mi
Registration #15	2024-02-20	50.377 mi
Registration #16	2025-02-20	51.377 mi
Registration #17	2026-02-20	52.377 mi
Registration #18	2027-02-20	53.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	1025 kg
Max. allowed weight	1510 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4EE7755427