





report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE S
Colour	Silver
Year of manufacture	2009
Top speed	125 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	330 Nm at 1.800 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-09-02

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-02-05
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	34
Total items failed	9

MOT #17		2024-01-31 15:58
MOT test	number	463502890511
Result		✓ Passed
Next expi	ry date	2025-02-05
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		(ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))

MOT #16	2024-01-31 10:47	
MOT test number	950396492993	
Result	X Failed	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill. marked. (5.3.6 (a) (i))		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1	.1.14 (a) (ii))	

MOT #15	2023-01-31 11:12
MOT test number	183416702365
Result	✓ Passed

CarCheck.co.uk page 3/14



AF09OJR

report date: 2024-03-29

MOT #14 2022-02-04 17:31

MOT test number 602036210958

Result ✓ Passed

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened AND REAR (1.1.14 (a) (ii))

MOT #13 2022-02-04 10:22

MOT test number 357869138842

Result X Failed

Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #12 2021-02-06 12:44

MOT test number 591555929521

Result
✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #11 2020-01-11 09:38

MOT test number 472693025833

MOT #10 2019-01-25 11:55

MOT test number 247320265852

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #9		2018-01-20 14:31
MOT test	number	426390185736
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #8		2017-01-11 11:13
MOT test	number	396867373017
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside front brake fluctuating, but not excessively (3.7.B.3)	
Advice	Engine covers obscuring some components	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.	5.1i)
Advice	Nearside front brake fluctuating, but not excessively (3.7.B.3)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Under covers obscuring some components	

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #7 2017-01-11 10:34 221802732870 **MOT** test number Result × Failed Advice Front Brake pad(s) wearing thin (3.5.1g) Advice Offside front brake fluctuating, but not excessively (3.7.B.3) Advice Engine covers obscuring some components Fail Offside Headlamp aim too high (1.8) Fail Exhaust emits an excessive level of metered smoke (7.4.B.3a) Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Nearside front brake fluctuating, but not excessively (3.7.B.3) Advice Advice Under covers obscuring some components Fail Nearside Headlamp aim too high (1.8) **Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6	2016-02-01 10:32
MOT test number	788402797309
Result	✓ Passed

MOT #5	2015-04-10 12:32
MOT test number	659270505124
Result	✓ Passed
Notice Under-trays fitted obscuring some underside components	

CarCheck.co.uk page 6/14



AF09OJR

report date: 2024-03-29

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Under-trays fitted obscuring some underside components

MOT #3 2014-04-04 11:22 **MOT** test number 425444594067 Result X Failed Advice Front Brake pad(s) wearing thin (3.5.1g) Notice Engine covers fitted obscuring some components in the engine bay Pass with rectification Centre Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d) **Advice** Rear Brake pad(s) wearing thin (3.5.1g) Notice Under-trays fitted obscuring some underside components

MOT #2	2013-04-16 16:40
MOT test number	845796003121
Result	✓ Passed
MOT #1	2012-03-16 10:02
MOT test number	286596072047
Result	✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	5 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner	history
O WILCI	,

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR	
have? Check it in the premium report and see all owner registrations. Download the full r	eport <u>here</u> .

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	UK PIE
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-21
Last registration	2024-01-31
Complete history	See info



Registration #1	2009-03-21	25 mi
Registration #2	2012-03-16	24.242 mi
Registration #3	2013-04-16	42.073 mi
Registration #4	2014-04-04	60.669 mi
Registration #5	2015-04-10	75.299 mi
Registration #6	2016-02-01	87.094 mi
Registration #7	2017-01-11	91.779 mi
Registration #8	2017-01-11	91.779 mi
Registration #9	2018-01-20	96.056 mi
Registration #5	2010 01 20	
Registration #10	2010 01 20	11.77 66
	2010 01 20	71,777 es
Registration #10	2010 01 20	77,777 es
Registration #10 Registration #11	2010 01 20	71,777 est 21,777 est 21,777 est 21,777 est
Registration #10 Registration #11 Registration #12		11.77 mi 11.77 mi 11.77 mi
Registration #10 Registration #11 Registration #12 Registration #13		11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14		11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14 Registration #15		11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea

More info >

CarCheck.co.uk page 13/14



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	61 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0901271244366G

CarCheck.co.uk page 14/14