





report date: 2024-03-29

General information

Make	BMW
Model	114 114I SE
Colour	Black
Year of manufacture	2015
Top speed	121 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	180 Nm at 1.100 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



Internet history

	-	4	-	-	1
ᆮ	п	ш	г١	,	_

ciitiy 1	
Date	2021-08-31
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-12
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	20
Total items failed	4

MOT #8	2024-02-13 16:52
MOT test number	485585436448
Result	✓ Passed
Next expiry date	2025-02-12

мот #	7	2024-02-12 16:51
MOT to	est number	697992374244
Result		X Failed
Fail	Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))	
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
Fail	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	

MOT #6	2022-10-01	l 10:55
MOT test	number 7886653	355726
Result	✓ I	Passed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #5		2021-01-30 16:49
MOT test	number	674420849992
Result		✓ Passed
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	

MOT #4	2020-02-11 09:07
MOT test	number 249960946700
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge and worn bald on outer edge (5.2.3 (e))
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice (e))	Nearside Rear Tyre worn close to legal limit/worn on edge and has a nail in its inside edge (5.2.3
Advice	Nearside Rear Nail in tyre

MOT #3		2019-02-12 10:59
MOT test	number	527748002540
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Pass with rectification

Offside Front Headlamp aim too low (4.1.2 (a))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1

MOT test number

Result

Advice Engine bay coves and under trays fitted obscuring some testable items

Advice Vehicle tested under wet conditions

Advice Oil level low

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	12 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
	-
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>have the current and the full report have the current and the full report have the current and the full report have the current and previous owner(s) have this BMW? How many owners did not be all the current and previous owner(s) have the current and current and previous owner(s) have the current and current a</u>		ve?

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-25
Last registration	2024-02-13
Complete history	See info



Registration #1	2015-03-25	16 mi
Registration #2	2018-02-15	66.639 mi
Registration #3	2019-02-12	75.745 mi
Registration #4	2019-02-12	75.745 mi
Registration #5	2020-02-11	82.422 mi
Registration #6		11.777 es
Registration #7		
3		0.00 44
Registration #8		0.074
		1.77 m

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

		_		
- I) i m	ension	ne Ki	WAIG	ht
$ \nu$	CHOICH	13 X	WCIG	

Width	1765 mm
Height	1421 mm
Length	4324 mm
Wheel base	2690 mm
Kerb weight	1295 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	52 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	A485J930

CarCheck.co.uk page 12/12