



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO E (55BHP)
Colour	Black
Year of manufacture	2007
Top speed	94 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	138 g/km
CO2 label	E





MOT history

MOT expiry date	2024-05-14
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	22
Total items failed	12

MOT #17	2023-05-15 10:52
MOT test number	818935490045
Result	✓ Passed
Next expiry date	2024-05-14
Advice	Exhaust noisy (8.1.1 (a))
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

MOT #16	2022-04-04 13:10
MOT test number	369262959249
Result	✓ Passed
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Inner edge worn through tread rubber - close to cord exposure. (5.2.3 (e))

**MOT #15**

2022-04-01 08:27

MOT test number

830865541857

Result**✗ Failed**

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Fail Exhaust has a major leak of exhaust gases (6.1.2 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Inner edge worn through tread rubber - close to cord exposure. (5.2.3 (e))

Fail Offside Side repeater not working (4.4.1 (a) (ii))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #14

2021-04-07 15:40

MOT test number

303054768358

Result**✓ Passed****MOT #13**

2019-11-25 15:08

MOT test number

979161344000

Result**✓ Passed**

Minor Offside Front Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Radiator insecure but not lightly to fall out, but may cause other damage

**MOT #12**

2019-11-20 10:30

MOT test number

719469611828

Result

✗ Failed

Fail

Nearside Front Direction indicator not working (4.4.1 (a) (ii))

Minor

Offside Front Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification

Front Registration plate missing (0.1 (a))

Advice

Radiator insecure but not lightly to fall out, but may cause other damage

Pass with rectification

Offside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification

Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Minor

Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11

2019-02-15 09:29

MOT test number

147921897136

Result

✓ Passed

Advice

Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor

Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10

2018-04-18 10:08

MOT test number

374740915400

Result

✓ Passed

**MOT #9** 2017-04-12 10:02**MOT test number** 923665043873**Result** ✓ Passed**MOT #8** 2016-04-25 09:48**MOT test number** 864306677494**Result** ✓ Passed**MOT #7** 2015-04-22 12:30**MOT test number** 159602015168**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-04-23 13:21**MOT test number** 557293614107**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #5** 2013-04-22 11:10**MOT test number** 717142013174**Result** ✓ Passed**MOT #4** 2012-04-24 11:44**MOT test number** 118715812187**Result** ✓ Passed**MOT #3** 2011-04-18 13:10**MOT test number** 217308801123**Result** ✓ Passed



MOT #2	2011-04-18 09:53
MOT test number	955588201186
Result	✗ Failed
Fail	Rear Direction indicators incorrect colour (1.4.A.2f)
Fail	Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2010-04-27 11:52
MOT test number	584827010160
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
14 May 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	14 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-04-27
Last registration	2023-05-15
Complete history	See info



Registration #1	2007-04-27	8 mi
Registration #2	2010-04-27	15.699 mi
Registration #3	2011-04-18	20.194 mi
Registration #4	2011-04-18	20.194 mi
Registration #5	2012-04-24	25.290 mi
Registration #6	2013-04-22	30.034 mi
Registration #7	2014-04-23	66.507 mi
Registration #8	2015-04-22	37.189 mi
Registration #9	2016-04-25	40.209 mi
Registration #10	2016-05-20	55.377 mi
Registration #11	2016-05-20	55.377 mi
Registration #12	2016-05-20	55.377 mi
Registration #13	2016-05-20	55.377 mi
Registration #14	2016-05-20	55.377 mi
Registration #15	2016-05-20	55.377 mi
Registration #16	2016-05-20	55.377 mi
Registration #17	2016-05-20	55.377 mi
Registration #18	2016-05-20	55.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1186 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BMD194531