



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Silver
Year of manufacture	2007
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F





MOT history

MOT expiry date	2024-10-22
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	25
Total items failed	2

MOT #16	2023-10-23 13:45
MOT test number	325619280037
Result	✓ Passed
Next expiry date	2024-10-22
Minor	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15	2022-07-06 09:04
MOT test number	323082867700
Result	✓ Passed

MOT #14	2021-09-03 16:32
MOT test number	526671913800
Result	✓ Passed

**MOT #13**

2020-08-20 11:02

MOT test number

702351993487

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #12

2019-08-29 09:32

MOT test number

708231597402

Result

✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #11

2018-08-17 09:18

MOT test number

921122118764

Result

✓ Passed

- Minor** Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Minor** Nearside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #10** 2017-08-21 13:49**MOT test number** 946048350852**Result** ✓ Passed

- Advice** Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside Front tyre inner side wall perishing
- Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #9 2016-08-18 12:38**MOT test number** 205820963300**Result** ✓ Passed**MOT #8** 2015-08-25 10:41**MOT test number** 489837235218**Result** ✓ Passed

- Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #7 2014-09-02 15:41**MOT test number** 717675044278**Result** ✓ Passed**MOT #6** 2013-08-20 11:56**MOT test number** 386862233265**Result** ✓ Passed**MOT #5** 2012-09-06 16:15**MOT test number** 225070252230**Result** ✓ Passed

**MOT #4** 2012-09-06 16:15**MOT test number** 478820852219**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2011-09-08 17:46**MOT test number** 365891951272**Result** ✓ Passed**Notice** Nearside front tyre sidewall deteriorating**Notice** Offside rear tyre sidewall deteriorating**MOT #2** 2011-09-08 16:48**MOT test number** 847731151227**Result** ✗ Failed**Notice** Nail in nearside rear tyre**Notice** Offside front tyre sidewall deteriorating and nail in tread**Fail** Nearside Stop lamp not working (1.2.1b)**Notice** Nearside front tyre sidewall deteriorating**Notice** Offside rear tyre sidewall deteriorating**MOT #1** 2010-09-06 09:44**MOT test number** 751339340298**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
22 October 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	22 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 EJ57OVA
Plate since	2024-03-29
Current registration	 EJ57OVA
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-10-18
Last registration	2023-10-23
Complete history	See info



Registration #1	2007-10-18	17 mi
Registration #2	2010-09-06	20.253 mi
Registration #3	2011-09-08	28.133 mi
Registration #4	2011-09-08	28.133 mi
Registration #5	2012-09-06	35.893 mi
Registration #6	2013-08-20	41.572 mi
Registration #7	2014-09-02	43.897 mi
Registration #8	2015-08-25	46.098 mi
Registration #9	2016-08-25	48.299 mi
Registration #10	2017-08-25	50.500 mi
Registration #11	2018-08-25	52.701 mi
Registration #12	2019-08-25	54.902 mi
Registration #13	2020-08-25	57.103 mi
Registration #14	2021-08-25	59.304 mi
Registration #15	2023-10-23	61.505 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 313622