





report date: 2024-03-28

General information

Make	SUZUKI
Model	GRAND VITARA 16V
Colour	Grey
Year of manufacture	2008
Top speed	106 mph
0 - 60 mph	13.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	183 Nm at 4.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.3 mpg
Consumption extra urban	35.8 mpg
Consumption combined	30.1 mpg
CO2 emission	217 g/km
CO2 label	K



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-05-26

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date

MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	8
Total items failed	2
MOT #15	2021-09-04 11:59
MOT test number	679352327189
Result	✓ Passed
Next expiry date	2022-09-03
MOT #14	2021-06-29 09:05
MOT test number	176606774343
Result	✓ Passed
MOT #13	2021-04-29 11:59

2022-09-03

MOT #13	2021-04-29 11:59
MOT test number	258361746901
Result	✓ Passed

MOT #12	2020-11-30 12:23
MOT test number	830534952696
Result	✓ Passed

MOT #11	2020-07-06 11:41
MOT test number	797357609289
Result	✓ Passed

CarCheck.co.uk page 3/12



Result

SA08BZO

report date: 2024-03-28

✓ Passed

MOT #10

MOT test number

Result

Pass with rectification

Offside Headlamp aim too low (4.1.2 (a))

Pass with rectification

Nearside Headlamp aim too low (4.1.2 (a))

MOT #9 2019-05-13 16:34 **MOT** test number 193210010962 Result ✓ Passed **Advice** Brake pipe corroded, covered in grease or other material both o/s and n/s front to rear (1.1.11 (c)) **Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i)) Front Brake pipe corroded, covered in grease or other material both (1.1.11 (c)) Advice **Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i)) **Advice** Fuel Pipe/s corroded

****	****
MOT #8	2018-04-20 08:08
MOT test number	303441310980
Result	✓ Passed
MOT #7	2017-05-05 13:53
MOT test number	406912539779

MOT #6	2016-05-13 12:44
MOT test number	246084843306
Result	√ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5		2015-01-06 10:46
MOT test	number	597786005058
Result		✓ Passed
MOT #4		2014-01-22 09:59
MOT test	number	668902724060
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Front discs corroded	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	

MOT #3	2013-01-23 09:12
MOT test number	609213623060
Result	✓ Passed
MOT #2	2012-01-24 09:53
MOT test number	215904722051
Result	✓ Passed
MOT #1	2011-02-08 09:00
MOT test number	748999531032
Result	√ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax expired: 1 September 2021

X MOT

Expired: 3 September 2022

Tax status	Expired at 1 September
Days left	970 days too late
MOT expiry date	3 September 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	,
Current registration	NIE UK
Plate since	
Current registration	UK NIV.
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-03-01
Last registration	2021-09-04
Complete history	See info



Registration #1	2008-03-01	13 mi
Registration #2	2011-02-08	21.223 mi
Registration #3	2012-01-24	26.319 mi
Registration #4	2013-01-23	30.884 mi
Registration #5	2014-01-22	35.006 mi
Registration #6	2015-01-06	37.321 mi
Registration #7	2016-05-13	42.648 mi
Registration #8	2017-05-05	52.179 mi
Registration #9	2018-04-20	59.820 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.70 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1695 mm
Length	4470 mm
Wheel base	2640 mm
Kerb weight	1595 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	J20A-460632

CarCheck.co.uk page 12/12