



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF MATCH TDI 105
Colour	Black
Year of manufacture	2008
Top speed	116 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-22
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	33
Total items failed	16

MOT #21 2024-03-15 09:13

MOT test number 264301355553

Result ✓ Passed

Next expiry date 2025-03-22

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** N/s mirror mounted wing repeater damaged and dim in operation
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement split and perished (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #20 2023-03-16 11:16

MOT test number 125872485215

Result ✓ Passed

MOT #19 2022-03-16 12:04

MOT test number 250985359987

Result ✓ Passed

- Advice** Heavy surface corrosion rear subframe
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #18**

2022-03-15 13:34

MOT test number

657148244908

Result**✗ Failed**

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Heavy surface corrosion rear subframe
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #17

2021-03-23 13:57

MOT test number

103944172595

Result**✓ Passed**

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect creaking (5.3.2 (b))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #16

2021-03-22 13:47

MOT test number

518115071764

Result**✗ Failed**

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect creaking (5.3.2 (b))
- Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Central Exhaust system insecure (6.1.2 (a))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front tyre worn inner edge

**MOT #15**

2020-07-31 07:48

MOT test number

825599013273

Result

✓ Passed

- Advice** Parking brake has travel
- Advice** Damage to osr quarter
- Advice** Front disc lipped
- Advice** Damage to osr Lense
- Advice** Oil leak
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #14

2020-07-28 14:13

MOT test number

589808363749

Result

✗ Failed

- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Oil leaking excessively from engine (8.4.1 (a) (i))
- Advice** Offside Rear lamp damage
- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Bumper insecure (6.1.4 (a) (i))

**MOT #13** 2019-08-01 14:14**MOT test number** 650718495483**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))**MOT #12** 2018-08-01 10:06**MOT test number** 182851148970**Result** ✓ Passed**MOT #11** 2017-09-27 15:15**MOT test number** 388175582056**Result** ✓ Passed**MOT #10** 2017-01-09 10:29**MOT test number** 362684763050**Result** ✓ Passed**MOT #9** 2017-01-09 10:29**MOT test number** 300787753280**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**MOT #8** 2016-01-08 12:50**MOT test number** 153687852131**Result** ✓ Passed

**MOT #7** 2014-08-07 12:57**MOT test number** 915629714253**Result** ✓ Passed**MOT #6** 2014-08-07 12:57**MOT test number** 605719914244**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #5** 2013-07-29 10:08**MOT test number** 866710213251**Result** ✓ Passed**MOT #4** 2012-07-20 12:07**MOT test number** 425282002250**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-07-29 12:23**MOT test number** 659620011286**Result** ✓ Passed**MOT #2** 2011-06-22 10:48**MOT test number** 399673371116**Result** ✓ Passed



MOT #1	2011-06-22 10:48
MOT test number	318153571130
Result	✗ Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
22 March 2025

Tax status	Valid until 1 September
Days left	126
MOT expiry date	22 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	VE08WRK
Plate since	2015-05-29
Current registration	VE08WRK
Plate since	2015-05-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-07-14
Last registration	2024-03-15
Complete history	See info



Registration #1	2008-07-14	18 mi
Registration #2	2011-06-22	72.784 mi
Registration #3	2011-07-29	72.908 mi
Registration #4	2012-07-20	83.913 mi
Registration #5	2013-07-29	97.310 mi
Registration #6	2014-08-07	110.053 mi
Registration #7	2016-01-08	127.392 mi
Registration #8	2017-01-09	140.555 mi
Registration #9	2017-01-09	140.555 mi
Registration #10	2017-09-27	146.717 mi
Registration #11	2018-08-01	160.010 mi
Registration #12	2019-01-01	160.010 mi
Registration #13	2019-01-01	160.010 mi
Registration #14	2019-01-01	160.010 mi
Registration #15	2019-01-01	160.010 mi
Registration #16	2019-01-01	160.010 mi
Registration #17	2019-01-01	160.010 mi
Registration #18	2019-01-01	160.010 mi
Registration #19	2019-01-01	160.010 mi
Registration #20	2019-01-01	160.010 mi
Registration #21	2019-01-01	160.010 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1251 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BXE B29276