





report date: 2024-03-29

General information

Make	BMW
Model	318 320I M SPORT
Colour	Blue
Year of manufacture	2012
Top speed	142 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	210 Nm at 4.250 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-14

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-06-01
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	12
Total items failed	11

MOT #12	2023-06-02 16:26
MOT test number	622483738160
Result	✓ Passed
Next expiry date	2024-06-01
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #11	2023-05-30 07:40
MOT test number	157566080718
Result	X Failed
Fail Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Fail Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Offside Rear Service brake excessively binding (1.2.1 (f))	
Fail Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Offside Front Road wheel badly distorted (5.2.2 (c) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #10

MOT test number

897892518047

Result

Advice Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

MOT test number

Result

MOT test number

Result

MOT #8

2020-11-10 15:22

MOT test number

934825962754

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT test number

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #6
 2018-05-31 14:54

 MOT test number
 478109164721

 Result
 ✓ Passed

 MOT #5
 2017-06-01 13:53

 MOT test number
 544069874553

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4 2016-06-06 15:53

MOT test number 465607928687

MOT #3 2016-02-08 15:32

MOT test number 844313677430

Result ✓ Passed

MOT #2 2016-02-08 13:39

MOT test number 439420325019

Result X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Front registration plate character(s) likely to be misread (6.3.4b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1 2015-02-19 12:35

MOT test number 418160855097

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	1 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report I	
THE STATE OF THE S	

	More info >
Plate changes	,
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	OK SILE
Plate since	
Current registration	AK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-03-01
Last registration	2023-06-02
Complete history	See info



Registration #1	2012-03-01	18 mi
Registration #2	2015-02-19	21.689 mi
Registration #3	2016-02-08	31.970 mi
Registration #4	2016-02-08	31.972 mi
Registration #5	2016-06-06	35.251 mi
Registration #6	2017-06-01	46.266 mi
Registration #7	2018-05-31	56.967 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1384 mm
Length	4580 mm
Wheel base	2760 mm
Kerb weight	1595 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	63 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12,

Number of axles 2

Engine number A980J184