



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	COMBO 2300 L1H1 CDTi
Colour	Red
Year of manufacture	2013
Top speed	97 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-28
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-30
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	16
Total items failed	15

MOT #13	2023-08-31 09:44
MOT test number	253293409036
Result	✓ Passed
Next expiry date	2024-08-30
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #12**

2023-08-25 13:50

**MOT test number**

150459436250

**Result****✗ Failed****Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Front Headlamp aim too low (4.1.2 (a))**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Horn not working (7.7 (a))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #11**

2022-08-24 13:00

**MOT test number**

199966397041

**Result****✓ Passed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2022-08-24 10:23**MOT test number** 137178068863**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2021-08-26 12:49**MOT test number** 524948504849**Result** ✓ Passed**MOT #8** 2021-08-26 12:48**MOT test number** 854721876419**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #7** 2021-08-02 12:39**MOT test number** 799768961967**Result** ✗ Failed**Fail** Horn not working (7.7 (a) (ii))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #6** 2021-01-09 10:21**MOT test number** 673427977769**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Macpherson strut mounting corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Nearside Front Macpherson strut mounting damaged but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #5** 2019-07-11 12:28**MOT test number** 862883853489**Result** ✓ Passed**MOT #4** 2018-06-22 15:59**MOT test number** 199598170128**Result** ✓ Passed**MOT #3** 2018-06-19 15:44**MOT test number** 720543262223**Result** ✗ Failed**Fail** Offside Side repeater incorrect colour (4.4.3 (a))**Fail** Nearside Front Headlamp lens seriously defective (4.1.1 (b) (ii))**MOT #2** 2017-06-30 14:20**MOT test number** 141180942280**Result** ✓ Passed



MOT #1	2016-07-01 08:21
MOT test number	358997743371
Result	✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>HN13YNA</b>
Plate since	2019-03-29
Current registration	<b>HN13YNA</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-07-15
Last registration	2023-08-31
Complete history	<a href="#">See info</a>



Registration #1	2013-07-15	10 mi
Registration #2	2016-07-01	43.049 mi
Registration #3	2017-06-30	58.455 mi
Registration #4	2018-06-19	71.449 mi
Registration #5	2018-06-22	71.450 mi
Registration #6	2019-07-11	79.088 mi
Registration #7	2021-01-09	95.169 mi
Registration #8	2023-08-31	101.217 mi
Registration #9	2023-08-31	101.217 mi
Registration #10	2023-08-31	101.217 mi
Registration #11	2023-08-31	101.217 mi
Registration #12	2023-08-31	101.217 mi
Registration #13	2023-08-31	101.217 mi
Registration #14	2023-08-31	101.217 mi
Registration #15	2023-08-31	101.217 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Wheel base	2750 mm
Kerb weight	1290 kg
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	5
Number of axles	2
Engine number	263A20005059822 LN9