



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF SE TDI
Colour	Grey
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-01-09
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	40
Total items failed	6

MOT #15	2024-01-09 14:22
MOT test number	615136940001
Result	✓ Passed
Next expiry date	2025-01-09

MOT #14	2023-01-07 10:20
MOT test number	424636528370
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush split (5.3.4 (a) (i))
Advice	Undertrays fitted not allowing a complete inspection

MOT #13	2022-01-08 10:56
MOT test number	490916964608
Result	✓ Passed
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Rear shock absorber shroud insecure

MOT #12	2020-12-23 10:33
MOT test number	750623766992
Result	✓ Passed

**MOT #11**

2020-12-23 10:33

MOT test number

104716506295

Result

✗ Failed

Pass with rectification

Windscreen washer provides insufficient washer liquid (3.5 (a))

Pass with rectification

Offside Rear Stop lamp(s) all not working (4.3.1 (a) (iii))

MOT #10

2019-06-24 10:24

MOT test number

111078833345

Result

✓ Passed

Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #9

2018-07-06 15:31

MOT test number

884044870920

Result

✓ Passed

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



MOT #8 2017-07-07 09:23

MOT test number 325829115510

Result ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit 2.5mm (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit 3mm and perished (4.1.E.1)
- Advice** Rear Inner Brake pad(s) wearing thin 3mm approx (3.5.1g)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7 2017-07-07 09:23

MOT test number 627667224055

Result ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit 2.5mm (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit 3mm and perished (4.1.E.1)
- Advice** Rear Inner Brake pad(s) wearing thin 3mm approx (3.5.1g)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Pass with rectification** Offside Headlamp aim too high (1.8)
- Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Pass with rectification** Nearside Headlamp aim too high (1.8)

**MOT #6** 2016-07-05 11:22**MOT test number** 717916533374**Result** ✓ Passed

- Advice** Front brake discs lipped, pads 7mm
- Advice** Slight lip on rear brake discs, pads 6mm
- Advice** Sidewalls starting to crack on nearside rear tyre

MOT #5 2015-07-10 15:41**MOT test number** 899091295158**Result** ✓ Passed

- Notice** Both front tyres are wearing on inner edges

MOT #4 2014-07-04 13:54**MOT test number** 786145084124**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Notice** Nearside rear tyre splitting

**MOT #3** 2014-07-04 12:15**MOT test number** 528915484129**Result** ✗ Failed**Notice** Nearside rear tyre splitting**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Brake pad arning light on advise remove all wheels to check brakes**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #2** 2013-07-09 11:33**MOT test number** 796970293165**Result** ✓ Passed**MOT #1** 2012-06-06 15:53**MOT test number** 257848352495**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
9 January 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	9 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-05-15
Last registration	2024-01-09
Complete history	See info



Registration #1	2009-05-15	13 mi
Registration #2	2012-06-06	36.767 mi
Registration #3	2013-07-09	52.413 mi
Registration #4	2014-07-04	62.741 mi
Registration #5	2014-07-04	62.741 mi
Registration #6	2015-07-10	71.880 mi
Registration #7	2016-07-05	84.888 mi
Registration #8	2017-07-07	97.762 mi
Registration #9	2017-07-07	97.762 mi
Registration #10	2018-05-29	101.377 mi
Registration #11	2018-05-29	101.377 mi
Registration #12	2018-05-29	101.377 mi
Registration #13	2018-05-29	101.377 mi
Registration #14	2018-05-29	101.377 mi
Registration #15	2018-05-29	101.377 mi
Registration #16	2018-05-29	101.377 mi
Registration #17	2018-05-29	101.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1266 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CBD 106784