






report date: 2024-03-29

## General information

Make	VAUXHALL
Model	CROSSLAND TECH LINE NAV ECOTEC S/S
Colour	Black
Year of manufacture	2018
Top speed	112 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	68.9 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	93 g/km
CO2 label	A



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history

### Entry 2

Date 2023-04-05

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date 2021-08-17

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2025-04-18
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #6	2024-04-17 10:45
MOT test number	576601790979
Result	<b>✓</b> Passed
Next expiry date	2025-04-18

MOT #5		2024-04-12 10:46
MOT test	number	263302275730
Result		<b>X</b> Failed
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Both re-	ar discs (1.1.14 (a) (ii))
MAJOR the ingress	Nearside Front Outer Drive shaft joint constant velocity boot split or insecus of dirt $(6.1.7 (g) (ii))$	re, no longer prevents
MAJOR	Brake performance unable to be tested (1.2.1 (g))	
DANGER	Nearside Rear Inner Brake pad(s) less than 1.5 mm thick Pad metal t	to metal (1.1.13 (a) (ii))

MOT #4		2023-04-19 12:23
MOT test	number	206928674325
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii	i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3		2022-08-13 13:06
MOT test	number	406060697439
Result		✓ Passed
Advice	Front offside and nearside tyres wearing on edges	
Advice	Rear Brake disc worn, but not excessively offside and nearside (1.1.14 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing cracking between tre	ead (5.2.3 (d) (ii))
Advice	Rear Exhaust mounting defective detached from exhaust (6.1.2 (a))	

MOT #2	2021-08-17 20:11
MOT test number	873533145610
Result	✓ Passed
MOT #1	2021-04-06 11:49
MOT test number	766544341633
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	18 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

## Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.


#### Damage 1

Date	
Category	
Туре	

#### Damage 2

Damage 2	
Date	
Category	







**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloahere.	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NE NE
Plate since	
	Moro info

CarCheck.co.uk page 8/11



report date: 2024-03-29

## Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
011.1.6.	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-06-11
Last registration	2024-04-17
Complete history	See info



Registration #1	2018-06-11	24 mi
Registration #2	2021-04-06	20.233 mi
Registration #3		11.777 es
Registration #4	2021-08-17	23.278 mi
Registration #5	2022-08-13	32.054 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

# Safety ratings

NCAP rating	****
Adult	85%
Children	84%
Pedestrian	62%
Safety systems	57%
Overall rating	75%
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1605 mm
Length	4212 mm
Wheel base	2604 mm
Kerb weight	1214 kg
Max. allowed weight	1820 kg

# Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	10IBHT3118119 LEK

CarCheck.co.uk page 11/11